

H. B. Barron Vice President **Duke Energy Corporation** 

McGuire Nuclear Station 12700 Hagers Ferry Road Huntersville, NC 28078-9340 (704) 875-4800 OFFICE (704) 875-4809 FAX

September 25, 1998

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Subject: McGuire Nuclear Station, Unit 1

Docket 50-369

Inservice Inspection Report Twelfth Refueling Outage

Please find attached the Inservice Inspection Report for McGuire Unit 1, twelfth refueling outage. This report is submitted per the requirements of 10CFR50.55a and by incorporation Article IWA-6000 of the Section XI ASME Code, 1989 Edition.

Relief requests associated with this Inspection Report which have been submitted or which are under development are listed in Section 5.2.

Any questions should be directed to Julius Bryant, McGuire Licensing and Compliance at (704) 875-4162.

1 An Barre

H. B. Barron, Vice President McGuire Nuclear Station

Attachment

A047/

U. S. Nuclear Regulatory Commission Document Control Desk Page 2

CC: Mr. F. Rinaldi, Project Manager
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
One White Flint North, Mail Stop 9H3
Washington, D.C. 20555

Mr. Luis A. Reyes, Regional Administrator Region II U. S. Nuclear Regulatory Commission Atlanta Federal Center 61 Forsyth St., SW, Suite 23T85 Atlanta, G. 30303

Mr. Scott Shaeffer NRC Senior Resident Inspector McGuire Nuclear Station