



Log # TXX-88443  
File # 10110  
905.3  
Ref # 10CFR50.55(e)

William G. Council  
Executive Vice President

May 12, 1988

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D.C. 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)  
DOCKET NOS. 50-445 AND 50-446  
FLUX MAPPING SEAL TABLE RESTRAINTS  
SDAR: CP-85-40 (SUPPLEMENTAL REPORT)

Gentlemen:

On November 26, 1985, in our report logged TXX-4633, we notified you of a deficiency regarding the adequacy of restraints (provided for the flux mapping system) under seismic loads which we deemed reportable under the provisions of 10CFR50.55(e). Our last report was logged TXX-6713, dated September 3, 1987. This report is submitted to status the implementation of corrective actions.

In our report TXX-6713 we noted that the Unit 2 modifications would be completed by May 15, 1988. Unit 2 modifications have been rescheduled for completion by Unit 2 fuel load. No further reports are anticipated.

Very truly yours,

*W. G. Council*

W. G. Council

By: *J. S. Marshall*

J. S. Marshall  
Generic Licensing Manager

WJH/mgt

c - Mr. R. D. Martin - Region IV  
Resident Inspectors, CPSES (3)

8805180247 880512  
PDR ADOCK 05000445  
S DCD

IE27  
1/0