



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60127

DCD/DCB(RIDS)
PDR only

September 7, 1988

Docket No. 50-456
Docket No. 50-457

Mr. Barry M. Saunders
Nuclear Security Administrator
Commonwealth Edison Company
Post Office Box 767
Chicago, IL 60690-0767

Dear Mr. Saunders:

In response to your letter dated August 22, 1988, enclosed is a copy of NRC Inspection Report Nos. 50-456/88020; 50-457/83020 which discuss the Braidwood Inattentive Guard issue with Safeguards Information removed. This report is now a public document and you may provide it to Burns Security.

Sincerely,

Bruce A. Berson

Bruce A. Berson
Regional Counsel

Enclosure: As stated

cc w/enclosure:
(w/incoming ltr dtd 8/22/88)
DCD/DCB(RIDS) PDR Only

DFOI
1/1
Add: Region 3 Original

8809150048 880907
PDR ADOCK 05000456
PDC

~~SAFEGUARDS INFORMATION~~ ^{TON}

JUL 0 1 1988

EA-88-174
Docket No. 50-456
Docket No. 50-457

Commonwealth Edison Company.
ATTN: Mr. Cordell Reed
Senior Vice President
Post Office Box 767
Chicago, IL 60690

Gentlemen:

This refers to the special safeguards inspection conducted by Mr. T. J. Madeda of this office on June 20, 1988, of activities at the Braidwood Nuclear Power Station, Units 1 and 2, authorized by NRC Operating Licenses No. NPF-72 and No. NPF-77, and to the discussion of our findings with Mr. Querio and other members of your staff, at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements. You will be notified by separate correspondence of our decision regarding enforcement actions based on the findings of this inspection. No written response is required until you are notified of the proposed enforcement action.

Areas examined during this inspection concern a subject matter which is exempt from disclosure according to Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Consequently, our report of this inspection, will not be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Charles E. Norelius, Director
Division of Radiation Safety
and Safeguards

Enclosure: Inspection Reports
No. 50-456/88020(DRSS); and
No. 50-457/88020(DRSS)
(UNCLASSIFIED SAFEGUARDS INFORMATION)

See Attached Distribution

RIII
Madedaxcrr

RIII
Creed

RIII
Winds

RIII
Stapleton

RIII
Mallett

405
RIII
NORELIUS
7/1/88

~~Enclosure Contains
SAFEGUARDS INFORMATION
Upon Separation This
Page Is Decontrolled.~~

~~SAFEGUARDS INFORMATION~~

0807120064

~~SAFEGUARDS INFORMATION~~ TT

Commonwealth Edison Company

2

JUL 01 1988

Distribution

cc w/enclosure:

T. J. Maiman, Vice President,
PWR Operations
H. Bliss, Nuclear
Licensing Manager
S. Hunsader, Manager of Projects
M. Lohmann, Project Construction
and Startup Superintendent
R. E. Querio, Station Manager
P. L. Barnes, Regulatory
Assurance Supervisor
NRR/DRIS/SGB
NRR/DRIS/S1B
NRR/DLPQ/PEB
J. Lieberman, OE
L. Chandler, OGC
F. Miraglia, NRR

cc w/enclosure, w/o

UNCLASSIFIED SAFEGUARDS
INFORMATION:
DCD/DCB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
Braidwood
Resident Inspector, RIII Byron
D. W. Cassel, Jr., Esq.
Richard Hubbard
J. W. McCaffrey, Chief, Public
Utilities Division
H. S. Taylor, Quality Assurance
Division
E. Chan, OGC
G. Berry, OGC
Stephen P. Sands, NRR
The Honorable A. Dixon Callihan, ASLB
The Honorable Richard F. Cole, ASLB
The Honorable Ivan W. Smith, ASLB
The Honorable Gary J. Edles, ASLAP
The Honorable Dr. W. Reed Johnson, ASLAP
The Honorable Christine N. Kohl, ASLAP

~~Enclosure Contains
SAFEGUARDS INFORMATION
Upon Separation This
Page Is Decontrolled~~

~~SAFEGUARDS INFORMATION~~