

Tennessee Valley Authority, Post Office Box 2000, Soddy Daisy, Tennessee 37379-2000

Masoud Bajestani
Site Vice President
Sequoyah Nuclear Plant

September 28, 1998

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555


10 CFR 50.73

Gentlemen:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT (SQN)
UNIT 2 - DOCKET NO. 50-328 - FACILITY OPERATING LICENSES
DPR-79 - LICENSEE EVENT REPORT (LER) 50-328/1998001

The enclosed report provides details concerning an automatic turbine and reactor trip, resulting from a failure of the sudden pressure relay on the 'B' phase main transformer. This event is being reported in accordance with 10 CFR 50.73(a)(2)(iv) as an event that resulted in a automatic actuation of engineered safety features, including the reactor protection system.

Sincerely,


Masoud Bajestani

Enclosure
cc: See page 2

IE22/1

9810070097 980928
PDR ADOCK 05000328
S PDR

U.S. Nuclear Regulatory Commission
Page 2.
September 28, 1998

Enclosure

cc (Enclosure):

INPO Records Center
Institute of Nuclear Power Operations
700 Galleria Parkway
Atlanta, Georgia 30339-5957

Mr. R. W. Hernan, Project Manager
U.S. Nuclear Regulatory Commission
One White Flint, North
11555 Rockville Pike
Rockville, Maryland 20852-2739

NRC Resident Inspector
Sequoyah Nuclear Plant
2600 Igou Ferry Road
Soddy-Daisy, Tennessee 37379-3624

Regional Administrator
U.S. Nuclear Regulatory Commission
Region II
Atlanta Federal Center
61 Forsyth Street, SW, Suite 23T85
Atlanta, Georgia 30303-3415