



**Commonwealth Edison**  
 One First National Plaza, Chicago, Illinois  
 Address Reply to: Post Office Box 767  
 Chicago, Illinois 60690

May 11, 1988

Mr. T. E. Murley, Director  
 Office of Nuclear Reactor Regulation  
 U.S. Nuclear Regulatory Commission  
 Washington, DC. 20555

Attention: Document Control Desk

Subject: Braidwood Unit 2  
 Limitorque Operator Lubrication  
 NRC Docket No. ~~40-457~~ 50-457

Reference: (a) March 23, 1988 A.B. Davis to C. Reed (CAL-RIII-88-06)  
 (b) March 29, 1988 L.O. DelGeorge letter to T.E. Murley  
 (c) April 11, 1988 L.O. DelGeorge letter to T.E. Murley  
 (d) April 21, 1988 L.O. DelGeorge letter to T.E. Murley

Dear Mr. Murley:

Reference (a) summarized the NRC staff's understanding of actions that would be taken to address deficiencies in the existing grease installed in limitorque valve operators at Braidwood Unit 2. Reference (b), (c) and (d) provided additional details of these actions and included the commitment to change out the grease per the acceptance criteria presented in the submittals.

The purpose of this letter is to notify the NRC staff that at this time, the grease has been changed out in those Unit 2 valve operators specified in reference (c) and that the actions presented in reference (a) have been completed. Other commitments, related to this issue such as the completion of radiation testing, still remain in effect and are expected to be completed as previously scheduled.

Please address any question concerning this matter to this office.

Very truly yours,

S. C. Hunsader  
 Nuclear Licensing Administrator

/klj  
 cc: S. Sands (NRR)  
 W. Forney (RIII)  
 Braidwood Resident Inspector  
 4613K

*Bool  
 1/0*

8805190256 880511  
 PDR ADOCK 05000457  
 P DCD