



Carolina Power & Light Company

Brunswick Steam Electric Plant
P. O. Box 10429
Southport, NC 28461-0429
May 13, 1988

FILE: B09-13510C
SERIAL: BSEP/88-0475

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555

BRUNSWICK STEAM ELECTRIC PLANT UNIT 2
DOCKET NO. 50-324
LICENSE NO. DPR-62
SPECIAL REPORT PER TECHNICAL SPECIFICATION 3.7.7.2 AND
PURSUANT TO TECHNICAL SPECIFICATION 6.9.2 (2-SR-88-004)

Gentlemen:

During Unit 1 power operation concurrent with the Unit 2 1988 refueling/maintenance outage, a limiting condition for operation (LCO) was established, at 0005 hours on March 31, 1988, in order to permit removal from service of the fire suppression sprinkler header in the units' common Radiological Waste Control System waste drumming room. This was done to allow replacement of a leaking sprinkler head. Due to problems in the acquisition of required replacement parts, the 14-day time frame of the subject LCO was exceeded on April 14, 1988. The required repairs were subsequently completed and, at 0435 hours on April 16, 1988, the involved sprinkler header was returned to service.

Very truly yours,

C. R. Dietz, General Manager
Brunswick Steam Electric Plant

MJP/tlw

Enclosure

cc: Dr. J. N. Grace
Mr. E. D. Sylvester
BSEP NRC Resident Office

8805200266 880513
PDR ADOCK 05000324
S DCD

IE22
/o