

SEP 12 1988

In Reply Refer To:
Docket: STN 50-482/88-14

Wolf Creek Nuclear Operating Corporation
ATTN: Bart D. Withers
President and Chief Executive Officer
P.O. Box 411
Burlington, Kansas 66839

Gentlemen:

This forwards the final report of the Systematic Assessment of Licensee Performance (SALP) for the Wolf Creek Generating Station for the period March 1, 1987, through March 31, 1988. This final report includes:

1. The corrected SALP Board Report (errata sheet enclosed to document the basis for changes).
2. A summary of our July 20, 1988, meeting at Wolf Creek Generating Station (WCGS) to discuss the SALP Board Report.
3. Your August 19, 1988, response to the SALP Board Report.

I consider the corrective actions discussed in the July 20, 1988, SALP management meeting and in your August 19, 1988, written response to the SALP Board Report to be responsive to NRC concerns and recommendations. Your August 19 response identifies a number of factual errors in the SALP Board Report; accordingly, we have made corrections to the report where appropriate. However, I do not consider these corrections to warrant changes in any of the SALP performance categories.

Sincerely,
Original signed by
John M. Montgomery

Robert D. Martin
Regional Administrator

8809190206 880912
PDR ADOCK 05000482
G PNU

Enclosure:
Errata Sheet

cc:
Wolf Creek Nuclear Operating Corporation
ATTN: Otto Maynard, Manager
of Licensing
P.O. Box 411
Burlington, Kansas 66839

<i>df</i> RIV:PSA ATHowell;df 9/9/88	<i>df</i> SR::PSA B:artlett 9/9/88	<i>df</i> C:PSA DDChamberlain 9/9/88	<i>df</i> NRR PO'Connor 9/9/88	<i>df</i> NRR JCalvo 9/9/88	<i>df</i> D:DRSS RLBangart 9/9/88
<i>df</i> D:DRS JLilhoan 9/9/88	<i>df</i> D:DRP LJCallan 9/9/88	<i>df</i> RA RDMartin 9/9/88	<i>df</i> Reconcur DDChamberlain 9/12/88		

IE40

Wolf Creek Nuclear Operating
Corporation

-2-

Wolf Creek Nuclear Operating Corporation
ATTN: Gary Boyer, Plant Manager
P.O. Box 411
Burlington, Kansas 66839

Kansas Corporation Commission
ATTN: Robert D. Elliott, Chief Engineer
Fourth Floor, Docking State Office Building
Topeka, Kansas 66612-1571

Kansas Radiation Control Program Director

bcc to DMB (IE40)

bcc distrib. by RIV:

RRI
Section Chief (DRP/A)
RPB-DRSS
RIV File
MIS System
Project Engineer, DRP/A
P. O'Connor, NRR Project Manager
DRS
Records Center, INPO
R. L. Bangart
All RRI's at all RIV sites
Chairman L. W. Zech (MS: H-1144)
Comm. T. M. Roberts (MS: H-1149)
Comm. F. M. Bernthal (MS: H-1149)
Comm. K. M. Carr (MS: H-1149)
Comm. K. C. Rogers (MS: H-1149)
PAO, Region IV

R. D. Martin, RA
DRP
B. DeFayette, RIII
SRI, Callaway, RIII
RSTS Operator
Lisa Shea, RM/ALF
G. F. Sanborn, EO
J. Taylor, D/IE
J. Calvo, NRR

ERRATA SHEET

<u>Page</u>	<u>Correction/Basis</u>
17	Replaced with corrected page. Basis: This change was made based on the licensee's response to acknowledge that the delay in resolution of the control room access issue was not fully attributable to the licensee. The NRC Region IV position on this issue has since been provided to the licensee in NRC Inspection Report 50-482/8818 dated August 8, 1988. A meeting with NRC Region IV and licensee management may be scheduled for final resolution of this issue.
19	Replaced with corrected page. Basis: Factual changes based on licensee response.
24	Replaced with corrected page. Basis: Factual changes based on licensee response.
27	Replaced with corrected page. Basis: Factual changes based on licensee response.
30	Replaced with corrected page. Basis: Factual changes based on licensee response.
Table 1	Replaced with corrected page. Basis: Factual changes based on licensee response.
Page 4 of Table 2	Replaced with corrected page. Basis: Factual changes based on licensee response.