

Paul Fessler, P.E.
Assistant Vice President, Nuclear Operations

Fermi 2
6406 North Dixie Hwy., Newport, MI 48166
Tel: 734.586.5325

Detroit Edison



10CFR50.73

October 5, 1998
NRC-98-0135

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

Reference: Fermi 2
NRC Docket No. 50-341
NRC License No. NPF-43

Subject: Licensee Event Report (LER) No. 98-006

Pursuant to 10CFR50.73(a)(2)(i)(B), Detroit Edison is hereby submitting the enclosed LER No. 98-006. This LER addresses the failure of Main Steam Isolation Valves to meet the specified leakage limits of Technical Specification 3.6.1.2.

The following commitment is being made in this LER:

A supplement to this LER will be submitted to document the cause of the unacceptable leakage and results of repair or rework, and retesting. This supplement is expected to be submitted by November 15, 1998.

Please contact Norman K. Peterson at (734) 586-4258 if you have any questions.

Sincerely,

9810090087 981005
PDR ADOCK 05000341
S PDR

cc: Regional Administrator, Region III
B. L. Burgess
G. A. Harris
A. J. Kugler
M. V. Yudas, Jr.
Region III
Wayne County Emergency Management Division

11
IE22