



DUKE POWER

September 9, 1988

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: McGuire Nuclear Station, Unit 1
Docket No. 50-369
Licensee Event Report

Gentlemen:

Pursuant to 10 CFR 50.73 Sections (a)(1) and (d), a Licensee Event Report concerning a missed valve retest, that was discovered on August 8, 1988, was to have been submitted to the NRC September 12, 1988. Please be advised that due to unresolved concerns, the report will be delayed and submitted October 3, 1988. Should there be any questions, please contact Steve LeRoy of Duke Licensing at (704)373-6233.

Very truly yours,

Hal B. Tucker

SEL/326/mff

Attachment

xc: Dr. J. Nelson Grace
Regional Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta St., NW, Suite 2900
Atlanta, GA 30323

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, GA 30339

M&M Nuclear Consultants
1221 Avenue of the Americas
New York, NY 10020

American Nuclear Insurers
c/o Dottie Sherman, ANI Library
The Exchange, Suite 245
270 Farmington Avenue
Farmington, CT 06032

Mr. Darl Hood
U.S. Nuclear Regulatory Commission
Office of Nuclear Reactor Regulation
Washington, D.C. 20555

Mr. W.T. Orders
NRC Resident Inspector
McGuire Nuclear Station

IF22
/0