



Log # TXX-88679
File # 10110
908.3
Ref. # 10CFR50.55(e)

William G. Council
Executive Vice President

September 13, 1988

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)
DOCKET NOS. 50-445 AND 50-446
REACTOR COOLANT PUMP WIRING
SDAR: CP-88-07 (SUPPLEMENTAL REPORT)

Gentlemen:

On January 11, 1988, TU Electric letter logged TXX-88066 provided notification that the deficiency involving reactor coolant pump wiring was reportable under the provisions of 10CFR50.55(e). The latest report on this issue, logged TXX-88516, was submitted June 14, 1988. This supplemental report is submitted to update the corrective actions completion schedule.

TXX-88516 indicated that corrective actions (installation of isolation devices and re-routing of cable as non-Class 1E) for Unit 1 would be completed by September 13, 1988. Unit 1 corrective actions have been rescheduled for completion by December 15, 1988. The schedule for Unit 2 remains unchanged.

Very truly yours,

W. G. Council

W. G. Council

By: *J. S. Marshall*

J. S. Marshall
Generic Licensing Manager

WJH/mlh

c-Mr. R. D. Martin, Region IV
Resident Inspectors, CPSES (3)

8809190281 880913
PDR ADOCK 05000445
S PDC

*IE27
/10*