



10 CFR 50.73

**Boston Edison**

Pilgrim Nuclear Power Station  
Rocky Hill Road  
Plymouth, Massachusetts 02360-5599

October 2, 1998  
BECo Ltr. 2.98.132

U.S. Nuclear Regulatory Commission  
Attn.: Document Control Desk  
Washington, D.C. 20555

Docket No. 50-293  
License No. DPR-35

The enclosed Licensee Event Report (LER) 98-021-00, "Inadequate Fuel Supply For Emergency Diesel Generators," is submitted in accordance with 10 CFR Part 50.73.

The corrective actions necessary to resolve the design basis fuel supply concern addressed in the enclosed LER have not been determined, however, they will impact planned corrective actions for the single failure vulnerability concern discussed in LER 98-001-00.

Supplementary information for LER 98-001-00 regarding corrective actions, scheduled for submittal on September 30, 1998, will be deferred until the long term resolution for the fuel supply has been approved.

Please do not hesitate to contact me if there are any questions regarding this report.

J. F. Alexander  
Nuclear Assessment Group Manager

000046

KRD/JRH/dcg  
ler/9802100  
Enclosure: LER 98-021-00

1/1  
IE22

9810090218 981002  
PDR ADDCK 05000293  
S PDR

Boston Edison Company

cc: Mr. Hubert J. Miller  
Regional Administrator, Region I  
U.S. Nuclear Regulatory Commission  
475 Allendale Road  
King of Prussia, PA 19406

Sr. NRC Resident Inspector - Pilgrim Station

INPO Records  
700 Galleria Parkway  
Atlanta, GA 30339-5957

Standard BECo LER Distribution