

MAY 13 1988

Docket No. 50-334

License No. DPR-66

Duquesne Light Company
ATTN: Mr. J. D. Sieber
Vice President
Nuclear Group
Post Office Box 4
Shippingport, Pennsylvania 15077

Gentlemen:

Subject: Inspection No. 50-334/88-03

This refers to your letter dated April 4, 1988, in response to our letter dated March 4, 1988.

Thank you for informing us of the corrective and preventive actions documented in your letter. These actions will be examined during a future inspection of your licensed program.

Your cooperation with us is appreciated.

Sincerely,

Original Signed By:
William J. Lazarus

Ronald R. Bellamy, Chief
Facilities Radiological Safety
and Safeguards Branch
Division of Radiation Safety
and Safeguards

cc w/encl:

J. J. Carey, Executive Vice President, Operations
J. O. Crockett, General Manager, Corporate Nuclear Services
W. S. Lacey, General Manager, Nuclear Operations
N. R. Tonet, Manager, Nuclear Engineering
T. P. Noonan, Plant Manager
C. E. Ewing, QA Manager
K. D. Grada, Manager, Nuclear Safety
Public Document Room (PDR)
Local Public Document Room (LPDR)
Nuclear Safety Information Center (NSIC)
NRC Resident Inspector
Commonwealth of Pennsylvania

OFFICIAL RECORD COPY

RL BV 88-07 - 0001.0.0
04/29/88

880524020 880513
PDR ADOCK 05000334
Q DCD

IE 06

MAY 13 1988

bcc w/encl:
 Region I Docket Room (with concurrences)
 Management Assistant, DRMA (w/o encl)
 L. Tripp, DRP
 D. Limroth, DRP
 P. Tam, LPM, NRR
 R. Bores, DRSS
 T. Weadock

RI:DRSS
 Nimitz/sh

4/188
 s/3
 RLW

RI:DRSS
 Weadock

4/188
 s/3
 RLW
 for

RI:DRSS
 Shanbaky

5/14/88
 MS

OFFICIAL RECORD COPY

RL BV 88-03 - 0002.0.0
 04/29/88



Nuclear Group
P.O. Box 4
Shippingport, PA 15077-0004

Shan
= Nitz
Telephone (412) 393-6000

April 4, 1988

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555


Reference: Beaver Valley Power Station, Unit No. 1
Docket No. 50-334, License No. DPR-66
Inspection Report 88-03

Gentlemen:

In response to NRC correspondence dated March 4, 1988 and in accordance with 10 CFR 2.201, the attached reply addresses the Notice of Violation which was included with the referenced report.

If there are any questions concerning this response, please contact my office.

Very truly yours,


J. D. Sieber
Vice President
Nuclear Group

Attachment

cc: Mr. J. Beall, Sr. Resident Inspector
Mr. Ronald R. Bellamy, Chief Region I Facilities
Radiological Safety and Safeguards Branch
Mr. W. T. Russell, NRC Region I Administrator
Director, Safety Evaluation & Control (VEPCO)

~~8804120352~~ 200

DUQUESNE LIGHT COMPANY
Beaver Valley Power Station, Unit No. 1

Reply to Notice of Violation
Inspection 88-03
Letter dated March 4, 1988

VIOLATION (Severity Level IV; Supplement IV)

Description of Violation (88-03-02)

Technical Specification 6.11 states that "procedures for personnel radiation protection shall be prepared consistent with the requirements of 10 CFR Part 20 and shall be approved, maintained and adhered to for all operations involving personnel radiation exposure.

Procedure RP 8.1, Radiological Work Permit, Section 3.2.1.8, requires in part, that individuals sign the applicable RWP, "...signifying understanding and acceptance of the conditions and controls of the RWP."

Contrary to the above, on January 26, 1988, A Radiological Controls technician entered the Unit 1 containment while not dressed in accordance with the minimum anti-contamination clothing requirements of the applicable RWP. Specifically, the technician entered containment without a cloth hood, coveralls, or a second pair of shoecovers and gloves. The controlling RWP required anti-contamination clothing to include, as a minimum, hood, coveralls, and two pairs each of shoecovers and rubber gloves.

Corrective Action Taken

The Radiation Technician was disciplined for his failure to follow the requirements of the Radiological Work Permit.

A memorandum noting the violation and weaknesses identified at the inspection exit was circulated for Radiological Control personnel reviews. The memorandum noted that Radiological Control personnel will be held accountable for their actions and are to set an example for other radiation workers.

As required by 10 CFR 19.11, a copy of the Notice of Violation was posted, and a copy of this reply will be posted.

Action Taken to Prevent Recurrence

A copy of the entire Inspection Report is being circulated for review by Radiological Control personnel. Their review of the report and support to correct identified weaknesses should avoid further violations of this nature.

Date When Full Compliance Will be Achieved

Full compliance has been achieved at this time.

outage
personnel
(create Techs ?)