

DUKE POWER COMPANY
P.O. BOX 33189
CHARLOTTE, N.C. 28242

TELEPHONE
(704) 373-4531

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

May 18, 1988

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D. C. 20555

Subject: Catawba Nuclear Station
Docket Nos. 50-413 and 50-414
Steam Generator Tube Rupture Analysis

Dear Sir:

In my letter of December 7, 1987 concerning the same subject, it was indicated in Attachment 1 demonstration runs would be performed to ensure analysis assumptions were correct. The results of this effort were to be submitted by June 1, 1988. These demonstration runs have been delayed. The results will be provided by July 1, 1988.

Very truly yours,

H. B. Tucker

Hal B. Tucker

PGL/19/sbn

Attachments

xc: Dr. J. Nelson Grace, Regional Administration
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Mr. P. K. Van Doorn
NRC Resident Inspector
Catawba Nuclear Station

Dr. K. Jabbour
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

8805240043 880518
PDR ADOCK 05000413
P PDR

*A001
/10*