

Docket Nos. STN 50-454
and STN 50-455

April 22, 1988

Mr. Henry Bliss
Nuclear Licensing Manager
Commonwealth Edison Company
Post Office Box 767
Chicago, Illinois 60690

DISTRIBUTION

Docket File
NRC/Local PDRs
DCrutchfield
GHolahan
LLuther
LOlshan

OGC-Rockville
EJordan
JPartlow
ACRS (10)
PDIII-2 Plant File
PDIII-2 Rdg. File

Dear Mr. Bliss:

SUBJECT: RESPONSE TO BULLETIN 88-01 FOR BYRON STATION (TAC NOs. 67647 and 67648)

By letter dated April 8, 1988, you responded to NRC Bulletin No. 88-01 "Defects in Westinghouse Circuit Breakers" for Zion, Byron and Braidwood Stations. We have completed our review of your response for Byron and conclude that you have satisfied the requirements of Bulletin 88-01 for both the short-term and long-term inspections.

You have committed to inspect one entire division per refueling outage, completing the inspections in 1993. Although this schedule is acceptable, if any other outages of sufficient duration occur, you should attempt to perform inspections and possibly complete the program prior to 1993.

Sincerely,

Original Signed by/

Leonard N. Olshan, Project Manager
Project Directorate III-2
Division of Reactor Projects - III,
IV, V and Special Projects

cc:
See next page

PDIII-2:PM
LOlshan:bj
4/21/88

PDIII-2:LA
LLuther
4/21/88

PDIII-2:PD
DMuller
4/22/88

8805240214 880422
PDR / ADCK 05000454
PDR
Q



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

Docket Nos. STN 50-454
and STN 50-455

April 22, 1988

Mr. Henry Bliss
Nuclear Licensing Manager
Commonwealth Edison Company
Post Office Box 767
Chicago, Illinois 60690

Dear Mr. Bliss:

SUBJECT: RESPONSE TO BULLETIN 88-01 FOR BYRON STATION (TAC NOs. 67647 and 67648)

By letter dated April 8, 1988, you responded to NRC Bulletin No. 88-01 "Defects in Westinghouse Circuit Breakers" for Zion, Byron and Braidwood Stations. We have completed our review of your response for Byron and conclude that you have satisfied the requirements of Bulletin 88-01 for both the short-term and long-term inspections.

You have committed to inspect one entire division per refueling outage, completing the inspections in 1993. Although this schedule is acceptable, if any other outages of sufficient duration occur, you should attempt to perform inspections and possibly complete the program prior to 1993.

Sincerely,

A handwritten signature in cursive script that reads "Leonard N. Olshan".

Leonard N. Olshan, Project Manager
Project Directorate III-2
Division of Reactor Projects - III,
IV, V and Special Projects

cc:
See next page

Mr. Henry Bliss
Commonwealth Edison Company

Byron Station
Units 1 and 2

cc:

Mr. William Kortier
Atomic Power Distribution
Westinghouse Electric Corporation
Post Office Box 355
Pittsburgh, Pennsylvania 15230

Regional Administrator, Region III
U. S. Nuclear Regulatory
Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Michael Miller, Esq.
Sidley and Austin
One First National Plaza
Chicago, Illinois 60603

Mr. Michael C. Parker, Chief
Division of Engineering
Illinois Department of
Nuclear Safety
1035 Outer Park Drive
Springfield, Illinois, 62704

Mrs. Phillip B. Johnson
1907 Stratford Lane
Rockford, Illinois 61107

Joseph Gallo, Esq.
Hopkins and Sutter
Suite 1250
1050 Connecticut Avenue, N.W.
Washington, D. C. 20036

Ms. Lorraine Creek
Rt. 1, Box 182
Manteno, Illinois 60950

Douglass Cassel, Esq.
109 N. Dearborn Street
Suite 1300
Chicago, Illinois 60602

Dr. Bruce von Zellen
Department of Biological Sciences
Northern Illinois University
DeKalb, Illinois 61107

Ms. Pat Morrison
5568 Thunderidge Drive
Rockford, Illinois 61107

Mr. Edward R. Crass
Nuclear Safeguards & Licensing
Sargent & Lundy Engineers
55 East Monroe Street
Chicago, Illinois 60603

Attorney General
500 South 2nd Street
Springfield, Illinois 62701

U. S. Nuclear Regulatory Commission
Byron/Resident Inspectors Offices
4448 German Church Road
Byron, Illinois 61010

Chairman, Ogle County Board
Post Office Box 357
Oregon, Illinois 61061

ESI Review Coordinator
Environmental Protection Agency
Region V
230 S. Dearborn Street
Chicago, Illinois 60604