

Commonwealth Edison Company  
Braidwood Generating Station  
Route #1, Box 84  
Braceville, IL 60407-9619  
Tel 815-458-2801



October 6, 1998

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D.C. 20555

The enclosed Licensee Event Report (LER) from Braidwood Generating Station is being transmitted in accordance with 10 CFR 50.73(a)(2)(iv), which requires a 30 day report.

The following commitments were made in this LER:

- Maintenance contract specifications will be revised to establish requirements for housekeeping and material storage for outside work activities
- Benchmarking will be done with other sites/utilities to determine if additional improvements can be made to protect transformers/switchyards.
- Transformer isolation zones will be established with the intention of prohibiting the storage of materials in areas with increased potential to impact transformer operation.
- Operator rounds for the transformers and switchyard will be reviewed and revised as necessary to include specifics regarding storage in areas where there is a potential for transformers to be impacted.

This report is number 98-003-00, Docket Number 50-456.

If your staff has any questions or comments concerning this LER, please refer them to Terrence Simpkin, Braidwood Regulatory Assurance Supervisor, at (815) 458-2801, extension 2980.

Timothy J. Tulon  
Site Vice President  
Braidwood Nuclear Generating Station

Enclosure: Licensee Event Report No. 456-98-003-00

cc: Regional Administrator-USNRC, Region III  
NRC Senior Resident Inspector-Braidwood Station

IE22%

9810130080 981006  
PDR ADOCK 05000456  
S PDR