



231 W. Michigan, P.O. Box 2046, Milwaukee, WI 53201

(414) 221-2345

VPNPD-88-282
NRC-88-046

10 CFR 50.73

May 17, 1988

U. S. NUCLEAR REGULATORY COMMISSION
Document Control Desk
Washington, D. C. 20555


Gentlemen:

DOCKET 50-301
TRANSMITTAL OF LICENSE EVENT REPORT 88-001-00
POINT BEACH NUCLEAR PLANTS, UNIT 2

On May 10, 1988, Licensee Event Report (LER) 88-001-00, "Reactor Trip Due to Malfunction of Instrument Bus Power Supply Mechanical Interlock", was sent to the NRC with my letter serial NRC-88-043. Page 1 of the LER was inadvertently transmitted with certain information missing from the form. We are providing herewith a complete copy of the subject LER. Please replace the LER forms attached to my May 10, 1988 letter with the enclosed forms.

We apologize for any inconvenience this mistake may have caused you.

Very truly yours,


C. W. Fay
Vice President
Nuclear Power

Attachments

Copies to NRC Resident Inspector
NRC Regional Administrator - Region III

8805240299 880517
PDR ADOCK 05000301
S PDR

IER2
11