

APPENDIX A
NOTICE OF VIOLATION

Arkansas Power & Light Company
Arkansas Nuclear One, Unit 2

Docket: 50-368
Operating License: NPF-6

During an NRC inspection conducted on April 18-22, 1988, a violation of NRC requirements was identified. The violation involved failure to correctly follow procedures. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1987), the violation is listed below:

Technical Specification 6.8.1 requires written procedures be established and implemented for surveillance and test activities of safety-related equipment.

Procedure 1092.031, "Integrated Leak Rate Test," has been established in accordance with this Technical Specification. Appendix M of this procedure requires that manually operated valves be tagged at the valve when placed in the test position or verified in the test position.

Contrary to the above, Valve ZPS-5878 was tagged as having been placed and verified in the test position and the associated pipe cap removed. However, the valve and pipe cap were not found in the correct test position.

This is a Severity Level IV violation. (Supplement I)(368/8811-01)

Pursuant to the provisions of 10 CFR 2.201, Arkansas Power & Light Company is hereby required to submit to this office, within 30 days of the date of the letter transmitting this Notice, a written statement or explanation in reply, including for each violation: (1) the reason for the violation if admitted, (2) the corrective steps which have been taken and the results achieved, (3) the corrective steps which will be taken to avoid further violations, and (4) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending the response time.

Dated at Arlington, Texas,
this *16th* day of *May* 1988.