

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION III 801 WARRENVILLE ROAD LISLE, ILLINOIS 60532-4351

October 5, 1998

Mr. Oliver D. Kingsley
President, Nuclear Generation Group
Commonwealth Edison Company
ATTN: Regulatory Services
Executive Towers West III
1400 Opus Place, Suite 500
Downers Grove, IL. 60515

SUBJECT: BRAIDWOOD INSPECTION REPORT 50-456/98012(DRP);

50-457/98012(DRP)

Dear Mr. Kingsley:

On September 8, 1998, the NRC completed an inspection at your Braidwood Units 1 and 2 reactor facilities. The enclosed report presents the results of that inspection. During the six-week period covered by this inspection period, your conduct of activities was generally characterized by safety-conscious operations, sound engineering and maintenance practices, and careful radiological protection controls.

One non-cited violation is discussed in this report. This violation addresses your identification that on one occasion for 42 seconds no senior reactor operator was present in the control room with both units in operation which is a failure to meet Technical Specification manning requirements.

Several material condition problems directly affected plant operations during this inspection period. Most failures involved nonsafety-related equipment but occurred during evolutions such as a feedwater pump swap, reactor shutdown, and a loss of offsite power. These equipment failures did not have a profound impact but did complicate the evolutions.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and the enclosure will be placed in the NRC Public Document Room.

Sincerely,

Geoffrey E. Grant Director Division of Reactor Projects

Docket Nos.: 50-456; 50-457 License Nos.: NPF-72; NPF-77

Enclosure: Inspection Report 50-456/98012(DRP);

50-457/98012(DRP)

cc w/encl: M. Wallace, Senior Vice President

D. Helwig, Senior Vice President G. Stanley, PWR Vice President J. Perry, BWR Vice President

D. Farrar, Regulatory Services Manager

I. Johnson, Licensing Director

DCD - Licensing

T. Tulon, Site Vice President K. Schwartz, Station Manager

T. Simpkin, Regulatory Assurance Supervisor

R. Hubbard, MHB Technical Associates

N. Schloss, Economist

Office of the Attorney General

State Liaison Officer

Chairman, Illinois Commerce Commission

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and the enclosure will be placed in the NRC Public Document Room.

Sincerely,

/s/ Geoffrey E. Grant

Geoffrey E. Grant, Director Division of Reactor Projects

Docket Nos.: 50-456; 50-457 License Nos.: NPF-72; NPF-77

Enclosure: Inspection Report 50-456/98012(DRP);

50-457/98012(DRP)

cc w/encl: M. Wallace, Senior Vice President

D. Helwig, Senior Vice President G. Stanley, PWR Vice President J. Perry, BWR Vice President

D. Farrar, Regulatory Services Manager

I. Johnson, Licensing Director

DCD - Licensing

T. Tulon, Siz Vice President K. Schwartz, Station Manager

T. Simpkin, Regulatory Assurance Supervisor

R. Hubbard, MHB Technical Associates

N. Schloss, Economist

Office of the Attorney General

State Liaison Officer

Chairman, Illinois Commerce Commission

DOCUMENT NAME: G\BRA\BRA98012.drp

To receive a copy of this document, indicate in the box "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure

OFFICE	RIII	9	RIII	E	RIII	RIII
NAME	Tongue:nh		Jordan 911		Grant CXFCX	
DATE	09/30/98		09/36/98		DOX 198)	09/ /98

OFFICIAL RECORD COPY

Distribution:

SAR (E-Mail)
Project Mgr., NRR w/encl
J. Caldwell, RIII w/encl
C. Pederson, RIII w/encl
B. Clayton, RIII w/encl
SRI Braidwood w/encl
DRP w/encl
TSS w/encl
DRS (2) w/encl
RIII PRR w/encl
PUBLIC IE-01 w/encl
Docket File w/encl
GREENS
IEO (E-Mail)
DOCDESK (E-Mail)