

Douglas R. Gipson  
Senior Vice President, Nuclear Generation

Fermi 2  
6400 North Dixie Hwy., Newport, Michigan 48166  
Tel: 313.586.5201 Fax: 313.586.4172

**Detroit Edison**



10CFR50.73

October 8, 1998  
NRC-98-0136

U S Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington D C 20555

Reference: Fermi 2  
NRC Docket No. 50-341  
NRC License No. NPF-43

Subject: Licensee Event Report (LER) No. 98-008

Pursuant to 10CFR50.73(a)(2)(i)(B), Detroit Edison is hereby submitting the enclosed LER No. 98-008 which documents a condition prohibited by Technical Specification 3.4.3.2 for an inboard pressure isolation valve which did not meet the required leakage limits.

The following commitment is being made in this LER:

An evaluation of the soft seat examination results is being performed to assist in determining the periodicity for replacement of the soft seat.

Please contact Norman K. Peterson, Director Nuclear Licensing, at (734) 586-4258 if you have any questions.

Sincerely,

cc: Regional Administrator, Region III  
B. L. Burgess  
G. A. Harris  
J. Kugler  
V. Yudasz, Jr.  
Region III  
Wayne County Emergency Management Division

9810140164 981008  
PDR ADOCK 05000341  
S PDR

1/1  
IE 22