

UNITED STATES NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20565-0001

October 13, 1998

LICENSEE: Cleveland Electric Illuminating Company

FACILITY: Perry Nuclear Power Plant, Unit No. 1

SUBJECT: SUMMARY OF SEPTEMBER 10, 1998 MEETING ON FEEDWATER ISOLATION

PROVISIONS

On September 10, 1998, NRC staff met with representatives of Cleveland Electric Illuminating Company (CEI) in Rockville, Maryland. The purpose of the meeting was to discuss proposed changes to the design and licensing basis to the containment isolation provisions for the feedwater system. A list of the meeting participants is included as Enclosure 1. While there were no meeting handouts, the licensee provided an advance copy of their license amendment request dated September 9, 1998 (PY-CEI/NRR-2322L). This document has been entered into the public document room under accession number 9809140325.

The license amendment request was not available to the staff prior to the meeting. As indicated above, the licensee provided a copy of their submittal during the meeting. The meeting was requested by the licensee in order to meet the technical reviewers, provide an explanation of the submittal, and to answer any staff questions. The licensee stressed the importance of this submittal to support their seventh refueling outage (currently scheduled for April 1999) and requested staff approval prior to January 29, 1999.

The license amendment request relates to hydrostatic (water) testing of containment isolation check valves in the feedwater system. Isolation provisions for the feedwater penetrations take credit for three isolation valves. Two piston lift check valves are located immediately inside and outside of the containment penetration. A third, motor-operated gate valve is located further upstream, outside of containment. The current licensing basis relies on a water seal provided by the feedwater leakage control system (FWLCS). The FWLCS injects water between the two check valves and also between the outside check valve and gate valve. Due to the need for operator action to initiate this system and the time to fill the piping volume between the valves, the water seal will not be provided until approximately one hour following the postulated accident. In addition, for long-term isolation provisions for a postulated feedwater line break inside containment, reliance is placed upon the motor-operated gate valve to close.

The proposed technical specification change stipulates that water leakage from the feedwater motor-operated containment isolation valves will be added into the Primary Coolant Sources Outside of Containment Program, and therefore the feedwater check valves will not need to be included in the hydrostatic test program addressed by Surveillance Requirement 3.6.1.3.11. The licensee proposes to add dual power supplies to the motor-operated containment isolation valve and redirect FWLCS water to the gate valve bonnet and seat areas. The licensee stated that these changes would represent improvements to the currently approved containment isolation provisions.

100

The request was submitted pursuant to both 10 CFR 50.90 and 50.59. A significant portion of the meeting was devoted to understanding the current licensing basis for the feedwater penetrations and how the proposed changes represent an overall improvement to the existing isolation provisions. The staff noted that the licensing basis appeared unique in that 1) while credit was being taken for a water seal, it would take approximately one hour to provide this seal, and 2) long-term isolation provisions rely upon the closure of the motor-operated gate valves.

The staff acknowledged industry problems with leak testing of feedwater check valves for boiling water reactors and indicated that the review would support the licensee's outage plans.

Douglas V. Pickett, Senior Project Manager

Project Directorate III-2

Division of Reactor Projects III/IV
Office of Nuclear Reactor Regulation

Docket No. 50-440

Enclosure: List of Meeting Participants

cc w/encls: See next page

The request was submitted pursuant to both 10 CFR 50.90 and 50.59. A significant portion of the meeting was devoted to understanding the current licensing basis for the feedwater penetrations and how the proposed changes represent an overall improvement to the existing isolation provisions. The staff noted that the licensing basis appeared unique in that 1) while credit was being taken for a water seal, it would take approximately one hour to provide this seal, and 2) long-term isolation provisions rely upon the closure of the motor-operated gate valves.

The staff acknowledged industry problems with leak testing of feedwater check valves for boiling water reactors and indicated that the review would support the licensee's outage plans.

Original signed by:

Douglas V. Pickett, Senior Project Manager Project Directorate III-2 Division of Reactor Projects III/IV Office of Nuclear Reactor Regulation

Docket No. 50-440

Enclosure: List of Meeting Participants

cc w/encls: See next page

DISTRIBUTION

Hard Copy w/encls E-mail w/Encl 1

Docket File SCollins (SJC1)

PD III-2 Reading FMiraglia (FJM)
PUBLIC THiltz

GGrant, RIII BBoger

mail w/Enci 1 collins (SJC1) JKudrick EAdensam

> EThrom CBerlinger GHolahan

Hard Copy w/Encl 1
OGC
ACRS

DOCUMENT NAME: G:\PERRY\MTG9_10.SUM

To receive a copy of this document, indicate in the box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

	PM: PDIII-20 G	LA:PDIII-2 E	D:PDIII-2	IC		
Description of the last of the	DPickett	EBarnhill EB	SRichards	5002		
DATE	10/13/98	10/9/98	10//3/98		10/ /98	10/ /98

OFFICIAL RECORD COPY

The request was submitted pursuant to both 10 CFR 50.90 and 50.59. A significant portion of the meeting was devoted to understanding the current licensing basis for the feedwater penetrations and how the proposed changes represent an overall improvement to the existing isolation provisions. The staff noted that the licensing basis appeared unique in that 1) while credit was being taken for a water seal, it would take approximately one hour to provide this seal, and 2) long-term isolation provisions rely upon the closure of the motor-operated gate valves.

The staff acknowledged industry problems with leak testing of feedwater check valves for boiling water reactors and indicated that the review would support the licensee's outage plans.

Original signed by:

Douglas V. Pickett, Senior Project Manager Project Directorate III-2 Division of Reactor Projects III/IV Office of Nuclear Reactor Regulation

Docket No. 50-440

Enclosure: List of Meeting Participants

cc w/encls: See next page

DISTRIBUTION

Hard Copy w/encls E-mail w/Encl 1

Docket File SCollins (SJC1) JKudrick EAdensam
PD III-2 Reading FMiraglia (FJM) EThrom

PUBLIC THiltz CBerlinger GGrant, RIII BBoger GHolahan

Hard Copy w/Encl 1 OGC ACRS

DOCUMENT NAME: G:\PERRY\MTG9_10.SUM

To receive a copy of this document, indicate in the box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

OFFICE	PM: PDIII-20 C	LA:PDIII-2 E	D:PDIII-2 C		
The same and the same and the same and	DPickett	EBarnhill EB	SRichards SAG-		
DATE	10/13/98	10/9 /98	10//3/98	10/ /98	10/ /98

OFFICIAL RECORD COPY

L. Myers Centerior Service Company

CC:

Mary E. O'Reilly FirstEnergy -- A290 10 Center Road Perry, OH 44081

Resident Inspector's Office U.S. Nuclear Regulatory Commission P.O. Box 331 Perry, OH 44081-0331

Regional Administrator, Region III U.S. Nuclear Regulatory Commission 801 Warrenville Road Lisle, IL 60532-4531

Sue Hiatt OCRE Interim Representative 8275 Munson Mentor, OH 44060

Henry L. Hegrat
Regulatory Affairs Manager
Cleveland Electric Illuminating Co.
Perry Nuclear Power Plant
P.O. Box 97, A210
Perry, OH 44081

FirstEnergy Corporation Michael Beiting Associate General Counsel 76 S. Main Akron, OH 44308

Mayor, Village of North Perry North Perry Village Hall 4778 Lockwood Road North Perry Village, OH 44081

Donna Owens, Director
Ohio Department of Commerce
Division of Industrial Compliance
Bureau of Operations & Maintenance
6606 Tussing Road
P. O. Box 4009
Reynoldsburg, OH 43068-9009

Perry Nuclear Power Plant, Units 1 and 2

James R. Williams
Chief of Staff
Ohio Emergency Management Agency
2855 West Dublin Granville Road
Columbus, OH 43235-7150

Mayor, Village of Perry 4203 Harper Street Perry, OH 44081

Radiological Health Program Ohio Department of Health P.O. Box 118 Columbus, OH 43266-0118

Ohio Environmental Protection Agency DERR--Compliance Unit ATTN: Mr. Zack A. Clayton P.O. Box 1049 Columbus, OH 43266-0149

Chairman
Perry Township Board of Trustees
3750 Center Road, Box 65
Perry, OH 44081

State of Ohio Public Utilities Commission East Broad Street Columbus, OH 43266-0573

William R. Kanda, Jr., Plant Manager Cleveland Electric Illuminating Co. Perry Nuclear Power Plant P.O. Box 97, SB306 Perry, OH 44081

MEETING ATTENDEES

NRC AND CLEVELAND ELECTRIC ILLUMINATING COMPANY

FEEDWATER ISOLATION PROVISIONS

SEPTEMBER 10, 1998

CLEVELAND ELECTRIC ILLUMINATING CO.

Robert W. Schrauder Henry L. Hegrat Bradley S. Ferrell Tom Shega

SCIENTECH - NUS

Dave Studiey

NRC

Carl Berlinger
Jack Kudrick
Ed Throm
Y.S. (John) Huang
Doug Pickett