



Northern States Power Company

Monticello Nuclear Generating Plant
2807 West Hwy 75
Monticello, Minnesota 55362-9637

October 9, 1998

10 CFR Part 50
Section 50.73

US Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

LER 98-004

**Manual Scram Inserted Following Pressure Transient
Closes Air Ejector Suction Isolation Valves and Trips Offgas Recombiners**

The Licensee Event Report for this occurrence is attached. This report contains one new NRC commitment:

Training will be provided on the importance of performing thorough investigations should symptoms of a potential problem be identified. For example, all potential flow paths should be investigated if unusual odors are detected.

Please contact Tom Parker at (612) 295-1014 if you require further information.

Michael F Hammer
Plant Manager
Monticello Nuclear Generating Plant

c: Regional Administrator - III NRC
Sr Resident Inspector, NRC
NRR Project Manager, NRC
State of Minnesota, Attn: Kris Sanda

Attachment

9810150306 981009
PDR ADOCK 05000263
S PDR

150025

11
Jerr