

Log # TXX-88686 File # 10110 903.9 Ref. # 10CFR50.55(e)

September 14, 1988

William G. Counsil Executive Vice President

1.34

8

U. S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, D. C. 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES) DOCKET NOS. 50-445 AND 50-446 TUBE STEEL MANUFACTURING DEFECTS SDAR: CP-88-28 (INTERIM REPORT)

Gentlemen:

On March 14, 1988, TU Electric verbally notified your Mr. R. F. Warnick of a deficiency involving tube steel manufacturing defects. The last report on this issue, logged TXX-88562, was submitted July 15, 1988.

TU Electric is continuing the evaluation of this issue's impact upon the safety of plant operations. TU Electric's next report on this issue will be submitted no later than November 16, 1988.

Very truly yours,

4). G. Course

W. G. Counsil

By:

D. R. Woodlan Cocket Licensing Manager

> TE27 110

HAM/mlh

0

c-Mr. R. D. Martin, Region IV Resident Inspectors CPSES (3)

> 8809230171 880914 PDR ADOCK 05000445 S PNU

> > 400 North Olive Street LB 81 Dallas, Texas 7520?