Docket No. 50-282 Docket No. 50-306

Northern States Power Company ATTN: Mr. C. E. Larson Director of Nuclear Generation 414 Nicollet Mall Minneapolis, MN 55401

## Gentlemen:

This refers to the routine safety inspection conducted by Mr. I. T. Yin of this office on February 26-27, 1986, of activities at Prairie Island Nuclear Generating Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-42 and No. DPR-60 and to the discussion of our findings with Mr. G. D. Gore at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

8603110181 860306 PDR ADOCK 05000282 PDR PDR Original Signed by J. J. Charlists

J. J. Harrison, Chief Engineering Branch

Enclosure: Inspection Reports No. 50-282/86004(DRS); and No. 50-306/86004(DRS)

See Attached Distribution

RIII (U

Yin/mj

RIII

Danielson 3/6/86 RIII W

Harrison 3/6

1/1 IE01

## Distribution

cc w/enclosure:
E. L. Watzl, Plant Manager
DCS/RSB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII Prairie
Island
Resident Inspector, RIII Monticello
John W. Ferman, Ph.D.,
Nuclear Engineer, MPCA