



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

SEP 12 1988

Docket No. 50-346

Toledo Edison Company
ATTN: Mr. Donald C. Shelton,
Vice President Nuclear
Edison Plaza
300 Madison Avenue
Toledo, OH 43652

Gentlemen:

This refers to the routine safety inspection conducted by Messrs. P. M. Byron, D. C. Kosloff, L. Bell, L. Valenti, and P. J. Prescott of this office from July 1, through August 15, 1988 of activities at Davis-Besse Nuclear Power Station authorized by Facility Operating License No. NPF-3 and to the discussion of our findings with Mr. L. Storz at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

for Robert C. Knop
R. C. Knop, Chief
Reactor Projects Branch 3

Enclosure: Inspection Report
No. 50-346/88021(DRP)

See Attached Distribution

8809260010 880912
PDR ADOCK 05000346
Q PDC

IE01
1/1

SEP 12 1988

Distribution

cc w/enclosure:

L. Storz, Plant Manager

DCD/DCB (RIDS)

Licensing Fee Management
Branch

Resident Inspector, RIII

Harold W. Kohn, Ohio EPA

James W. Harris, State of
Ohio

Robert M. Quillin, Ohio
Department of Health

State of Ohio, Public
Utilities Commission