

Northeast
Nuclear Energy

Rope Ferry Rd. (Route 156), Waterford, CT 06385

Millstone Nuclear Power Station
Northeast Nuclear Energy Company
P.O. Box 128
Waterford, CT 06385-0128
(860) 447-1791
Fax (860) 444-4277

The Northeast Utilities System

OCT 15 1998

Docket No. 50-423

B17464

Re: 10 CFR 50.73(a)(2)(iv)

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555


Millstone Nuclear Power Station Unit No. 3
Licensee Event Report 98-038-00
"Manual Reactor Trip Due To High Conductivity In The Condensate System"

This letter forwards Licensee Event Report (LER) 98-038-00 (Attachment 2), documenting a condition that was determined reportable at Millstone Unit No. 3 on September 15, 1998. This LER is submitted pursuant to 10 CFR 50.73(a)(2)(iv). Northeast Nuclear Energy Company's (NNECO) commitments in response to this event are contained within Attachment 1 to this letter.

Should you have any questions regarding this submittal, please contact Mr. David A. Smith at (860) 437-5840.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY


M. H. Brothers
Vice President, Operations

1/1
IE22

9810200190 981015
PDR ADDCK 05000423
S PDR

Attachment: 1) NNECO's commitments in response to LER 98-038-00
2) LER 98-038-00

cc: H. J. Miller, Region I Administrator
A. C. Cerne, Senior Resident Inspector, Millstone Unit No. 3
J. W. Andersen, NRC Project Manager, Millstone Unit No. 3
E. V. Imbro, Director, Millstone ICAVP Inspections
Corrective Action Group Files (CR M3-98-4130)

RAL:rl

Docket No. 50-423
B17464

Attachment 1

Millstone Nuclear Power Station, Unit No. 3
NNECO's Commitments In Response To
LER 98-038-00

October 1998

List of Regulatory Commitments

The following table identifies those actions committed to by NNECO in this document. Please notify the Manager - Regulatory Compliance at the Millstone Nuclear Power Station Unit No. 3 of any questions regarding this document or any associated regulatory commitments.

Number	Commitment	Due
B17464-01	Operations Procedure OP 3316C, "Steam Generator Blowdown" was revised to ensure the blowdown receiver tank does not reach vacuum conditions during removal from service.	Complete
B17464-02	Revise appropriate operating procedures to incorporate new criteria for manual trip of reactor on high condensate discharge conductivity.	December 15, 1998

Docket No. 50-423
B17464

Attachment 2

Millstone Nuclear Power Station, Unit No. 3
NNECO's Submittal of
LER 98-038-00

October 1998