MAR 1 2 1986

Docket Nos. 50-443

License No. CPPR-135

Public Service of New Hampshire
ATTN: Mr. Robert J. Harrison
President and Chief Executive Officer
P. O. Box 330
Manchester, New Hampshire 03105

Gentlemen:

Subject: Inspection Report No. 50-443/86-11

This refers to the routine safety inspection conducted by Mr. R.A. McBrearty of this office on February 10 through 14, 1986 at Seabrook Station, Unit 1 of activities authorized by NRC License No. CPPR-135 and to the discussions of our findings held by Mr. McBrearty with Mr. P. Oikle of your staff at the conclusion of the inspection.

Areas examined during this inspection are described in the NRC Region I Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, measurements made by the inspector, and observations by the inspector.

Within the scope of this inspection, no violations were observed.

No reply to this letter is required. Your cooperation with us in this matter is appreciated.

Sincerely,

Original Signed By: Clifford J. Amlerson

Stewart D. Ebneter, Director Division of Reactor Safety

Enclosure: NRC Region I Inspection Report No. 50-443/86-11

8603170367 860312 PDR ADOCK 05000443

OFFICIAL RECORD COPY

IR SEABROOK 86-11 - 0001.0.0 03/07/86

JE01 11

cc w/encl:
John DeVincentis, Director, Engineering and Licensing
William B. Derrickson, Senior Vice President
Warren Hall, Operational Services Supervisor
Donald E. Moody, Station Manager - Seabrook Station
Gerald F. McDonald, Construction QA Manager
Public Document Room (PDR)
Local Public Document Room (LPDR)
Nuclear Safety Information Center (NSIC)
NRC Resident Inspector
State of New Hampshire

bcc w/encl:
Region I Docket Room (with concurrences)
Management Assistant, DRMA (w/o encl)
RRP Section Chief
Jane Grant, DRP

RI:DRS 101 fo RI:DRS 101 RI:DRS 1