



A Centenor Energy Company

Docket No. 50-346

License No. NPF-3

Serial No. 1531

May 25, 1988

DONALD C. SHELTON
Vice President—Nuclear
(419) 249-2300

United States Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: Response to Generic Letter 88-03, Resolution of Generic Safety Issue 93, "Steam Binding of Auxiliary Feedwater Pumps"

Gentlemen:

Pursuant to 10CFR50.54(f), this letter provides Toledo Edison's response to NRC Generic Letter 88-03, Resolution of Generic Safety Issue 93, "Steam Binding of Auxiliary Feedwater Pumps", dated February 17, 1988 (Log No. 2500). Previously, the United States Nuclear Regulatory Commission Office of Inspection and Enforcement issued IE Bulletin 85-01, Steam Binding of Auxiliary Feedwater Pumps (Log No. 1-1268, dated October 29, 1985). Toledo Edison responded to this IE Bulletin on February 28, 1986 (Serial No. 1-622) with regards to the Auxiliary Feedwater (AFW) System and on March 12, 1986 (Serial No. 1-627) with regards to the Motor Driven Feedwater Pump (MDFP) System.

The responses to IE Bulletin 85-01 discussed Toledo Edison's procedural requirements both for monitoring the AFW and MDFP piping temperatures for indication of possible backleakage and for restoring the pumps to operable status if steam binding were to occur. These procedural requirements are administratively controlled as commitments and will, therefore, be maintained.

This response satisfies the request of Generic Letter 88-03 and, through the committed implementation of the recommendations of IE Bulletin 85-01, is consistent with the resolution of Generic Safety Issue 93.

Very truly yours,

CAB:tlt

Enclosure

cc: A. W. DeAgazio, NRC/NRR Davis-Besse Project Manager
DB-1 Resident Inspector
A. B. Davis, Region III, Regional Administrator


A063
1/1

Docket No. 50-346
License No. NPF-3
Serial No. 1531
Enclosure
Page 1


RESPONSE TO GENERIC LETTER 88-03
RESOLUTION OF GENERIC SAFETY ISSUE 93,
"STEAM BINDING OF AUXILIARY FEEDWATER PUMPS"
FOR
DAVIS-BESSE NUCLEAR POWER STATION
UNIT NO. 1

This letter provides Toledo Edison's response to Generic Letter 88-03, Resolution of Generic Safety Issue 93, "Steam Binding of Auxiliary Feedwater Pumps" (Log No. 2500, dated February 17, 1988) confirming that procedures to detect and correct steam binding are in place and will be maintained.

By


D. C. Shelton, Vice President, Nuclear

Sworn to and subscribed before me this 25th day of May, 1988.


Notary Public, State of Ohio

NANCY L. DAMSCHRODER, Notary Public
OTTAWA COUNTY, OHIO
My Commission Expires Oct. 8, 1991