

ENCLOSURE 1

NOTICE OF VIOLATION

South Carolina Electric & Gas  
V. C. Summer Nuclear Station

Docket No. 50-395  
License No. NPF-12

The following violation was identified during an inspection conducted on April 1-30, 1988. The Severity Level was assigned in accordance with the Enforcement Policy (10 CFR Part 2, Appendix C).

Technical Specification 3.7.9.3, The Relay Room, requires that with the low pressure CO<sub>2</sub> system inoperable, within one hour establish a continuous fire watch with backup fire suppression equipment.


Contrary to the above, on April 26, 1988, the licensee failed to establish a continuous fire watch with backup suppression equipment in The Relay Room. The CO<sub>2</sub> system was tagged out at 5:35 a.m. for performance of Surveillance Test Procedure 128.331. At the time of the tagging operations personnel failed to compensate for the loss of CO<sub>2</sub> to The Relay Room. The error was discovered after 1 hour and 53 minutes. This violation is similar to a violation identified in Inspection Report No. 50-395/87-24.

This is a Severity Level IV violation, (Supplement I).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which will be taken to avoid further violations; and (4) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

FOR THE NUCLEAR REGULATORY COMMISSION



David M. Verrelli, Chief  
Reactor Projects Branch 1  
Division of Reactor Projects

Dated at Atlanta, Georgia  
this        day of May 1988