



Illinois Power Company
Clinton Power Station
P.O. Box 678
Clinton, IL 61727
Tel 217 935-5623
Fax 217 935-4632

Walter G. MacFarland IV
Senior Vice President
and Chief Nuclear Officer

U-603094
2C.220

October 19, 1998

Docket No. 50-461

10CFR50.73

Document Control Desk
Nuclear Regulatory Commission
Washington, D.C. 20555

Subject: Clinton Power Station - Unit 1
Licensee Event Report No. 1998-027-00

Dear Madam or Sir:

Enclosed is Licensee Event Report (LER) No. 1998-027-00: Failure to Perform Surveillance Testing on Division II 4.16 KV Bus Undervoltage Relay Within the Specified Frequency of the Technical Specifications Due to Inadequate Software Change Management. This report is being submitted in accordance with the requirements of 10CFR50.73.

The enclosed report contains the following commitments:

- Computer programs and reports used by Work Management will be identified, reviewed and added to the computer application management program as applicable.
- CPS No. 1011.06 will be revised to require that changes to computer generated reports, used to assist in surveillance scheduling and tracking, be verified and validated prior to use.
- Work Week Managers, Surveillance Coordinators, Shift Managers, and System Planners will be trained on the roles, responsibilities, and interfaces related to the surveillance test program.

Sincerely yours,

Walter G. MacFarland, IV
Senior Vice President and
Chief Nuclear Officer

9810260103 981019
PDR ADOCK 05000461
S PDR

JRF/krk

cc: NRC Clinton Licensing Project Manager
NRC Resident Office, V-690
Acting Regional Administrator, Region III, USNRC
Illinois Department of Nuclear Safety
INPO Records Center