



An Illinova Company

Illinois Power Company  
Clinton Power Station  
P.O. Box 678  
Clinton, IL 61727  
Tel 217 935-5623  
Fax 217 935-4632

Walter G. MacFarland IV  
Senior Vice President  
and Chief Nuclear Officer

U-603078  
2C.220

October 19, 1998

Docket No. 50-461

10CFR50.73

Document Control Desk  
Nuclear Regulatory Commission  
Washington, D.C. 20555

Subject: Clinton Power Station - Unit 1  
Licensee Event Report No. 1998-024-01

Dear Madam or Sir:

Enclosed is Licensee Event Report (LER) No. 1998-024-01: Failure to Perform Surveillance Testing on Division II 4.16 KV Bus Undervoltage Relay Within the Specified Frequency of the Technical Specifications Due to Personnel Error. This report is being submitted in accordance with the requirements of 10CFR50.73.

The enclosed report contains the following commitments:

- CPS No. 1011.06, "Routine Surveillance Tracking and Scheduling," will be revised to clarify the expectation of reviewing the Late Report at least once each work day.
- Revising CPS No. 1011.02, "Implementation and Control of Surveillance Testing," for the Supervisor of Scheduling to ensure adequate staffing of the Surveillance Coordinator position.

Sincerely yours,

Walter G. MacFarland, IV  
Senior Vice President and  
Chief Nuclear Officer

JRF/krk

9810260188 981019  
PDR ADOCV. 05000461  
S PDR

000041

IE221/1

Enclosure

cc: NRC Clinton Licensing Project Manager  
NRC Resident Office, V-690  
Regional Administrator, Region III, USNRC  
Illinois Department of Nuclear Safety  
INPO Records Center