6.1 RESPONSIBILITY

- 6.1.1 The Station Manager shall be responsible for overall unit operation and shall delegate in writing the succession to this responsibility during his absence.
- 6.1.2 The Shift Supervisor (or during his absence from the control room, a designated individual) shall be responsible for the control room command function. A management directive to this effect, signed by the Vice-President Nuclear Production shall be reissued to all Nuclear Production Department station personnel on an annual basis.

6.2 ORGANIZATION

OFFSITE

6.2.1 The offsite organization for unit management and technical support shall be as described in the FSAR, Chapter 13.

UNIT STAFF

- 6.2.2 The unit organization shall be as shown in the FSAR, Chapter 13, and:
 - Each on-duty shift shall be composed of at least the minimum shift crew composition shown in Table 6.2-1;
 - b. At least one licensed Operator for each unit shall be in the control room when fuel is in either reactor. In addition, while either unit is in MODE 1, 2, 3, or 4, at least one licensed Senior Operator shall be in the control room;
 - A Health Physics Technician[#] shall be on site when fuel is in either reactor;
 - d. All CORE ALTERATIONS shall be observed and directly supervised by either a licensed Senior Operator or licensed Senior Operator Limited to Fuel Handling who has no other concurrent responsibilities during this operation;
 - e. A site Fire Brigade of at least five members shall be maintained onsite at all times." The Fire Brigade shall not include three members of the minimum shift crew necessary for safe shutdown of the unit and any personnel required for other essential functions during a fire emergency; and

8604010142 860328 PDR ADOCK 05000369 PDR

[&]quot;The Health Physics Technician and Fire Brigade composition may be less than the minimum requirements for a period of time not to exceed 2 hours in order to accommodate unexpected absence, provided immediate action is taken to fill the required positions.