

ENCLOSURE 1

NOTICE OF VIOLATION

Virginia Electric and Power Company
North Anna Units 1 and 2

Docket Nos. 50-338 and 50-339
License Nos. NPF-4 and NPF-7

During the Nuclear Regulatory Commission (NRC) inspection conducted on July 16 - August 19, 1988, one violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1987), the violation is listed below:

- A. Technical Specification 6.8.1.a requires written procedures be established, implemented, and maintained covering access to the containment as documented in Appendix A of Regulatory Guide 1.33, Revision 2, February 1978.

Administrative Procedure (AP) 20.9, Containment Ingress and Egress, section 7, has a note stating "Each department will complete the applicable sections of attachment 1 as the steps are completed". Step 7.14 of AP 20.9 requires the health physics technician to determine the stay time using the sling psychrometer and document the wet and dry bulb temperatures and actual stay time on Attachment 1 of the procedure.

- a. Contrary to the above, the inspectors identified that the licensee had not documented the wet bulb temperature or calculated the stay time for the containment entries made on August 8, 1988, at 0924 and 1618. This determination was made based on a review of Attachment 1 of AP 20.9 used for the containment entries.
- b. Contrary to the above, during a containment entry made on August 9 the licensee failed to complete Attachment 1 of AP 20.9 as required by the procedure.

This is a Severity Level V violation (Supplement 1) and applied to Unit 1 only.

Pursuant to the provisions of 10 CFR 2.201, Virginia Electric and Power Company is hereby required to submit a written statement or explanation to the Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, DC 20555, with a copy to the Regional Administrator, Region II, and a copy to the NRC Resident Inspector, North Anna, within 30 days of the date of the letter transmitting this Notice. This reply should be clearly marked as a "Reply to a Notice of Violation" and should include (for each violation): (1) admission or denial of the violation, (2) the reason for the violation if admitted, (3) the corrective steps which have been taken and the results achieved, (4) the corrective steps which will be taken to avoid further violations, and (5) the date when full

Virginia Electric and Power Company 2
North Anna Units 1 and 2

Docket Nos. 50-338 and 50-339
License Nos. NPF-4 and NPF-7

compliance will be achieved. Where good cause is shown, consideration will be given to extending the response time. If an adequate reply is not received within the time specified in this Notice, an order may be issued to show cause why the license should not be modified, suspended, or revoked or why such other action as may be proper should not be taken.

FOR THE NUCLEAR REGULATORY COMMISSION

Original signed by
R. V. Crlenjak (for)

Bruce A. Wilson, Chief
Reactor Projects Branch 2
Division of Reactor Projects

Dated at Atlanta, Georgia
this 15th day of September 1988