

# CP&L

Carolina Power & Light Company

BRUNSWICK STEAM ELECTRIC PLANT

P. O. Box 10429

Southport, NC 28461-0429

March 26, 1986

FILE: B09-13510C  
SERIAL: BSEP/86-0340

Dr. J. Nelson Grace, Administrator  
U.S. Nuclear Regulatory Commission  
Suite 2900  
101 Marietta Street NW  
Atlanta, GA 30323

BRUNSWICK STEAM ELECTRIC PLANT UNIT 2

DOCKET NO. 50-324


LICENSE NO. DPR-62

SPECIAL REPORT PER TECHNICAL SPECIFICATION 3.7.8 AND  
PURSUANT TO TECHNICAL SPECIFICATION 6.9.2 (2-SR-86-003)

Dear Dr. Grace:

During an ongoing Unit 2 refueling/maintenance outage, concurrent with power operation of Unit 1, on February 23, 1986, at 0945, a fire barrier LCO was initiated to permit removal of penetration seal DG-1-117 in the Units 1 and 2 common Diesel Generator Building. This was done to replace Service Water System piping as part of a plant modification. Work relative to the penetration seal was completed and March 6, 1986, at 1530, functional status of the penetration seal was reestablished. While the subject LCO was in effect, appropriately stationed fire watches were maintained.

Very truly yours,



C. R. Dietz, General Manager  
Brunswick Steam Electric Plant

RMP/ag

Enclosure

cc: NRC Document Control Desk

8604100145 860326  
PDR ADOCK 05000324  
S PDR

IEE 1/0  
15612