

Duke Power Company
P.O. Box 33198
Charlotte, N.C. 28242

Hal B. Tucker
Vice President
Nuclear Production
(704)373-4531



DUKE POWER

September 27, 1988

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: McGuire Nuclear Station, Unit 1
Docket No. 50-369
Licensee Event Report Delay

Gentlemen:

Pursuant to 10CFR 50.73 Sections (a)(1) and (d), a Licensee Event Report concerning a containment spray (NS) system valve that aligns the NS Pump A and B to the containment sump and could not be opened from the control room as designed was to have been submitted October 13, 1988. Please be advised that due to unresolved concerns, the report will be delayed and submitted October 13, 1988.

Should there be any questions, please contact S.E. LeRoy at (704)373-6233.

Very truly yours,

Hal B. Tucker

SEL/337/mmr

Attachment

xc: Dr. J. Nelson Grace
Regional Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta St., NW, Suite 2900
Atlanta, GA 30323

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, GA 30339

M&M Nuclear Consultants
1221 Avenue of the Americas
New York, NY 10020

American Nuclear Insurers
c/o Dottie Sherman, ANI Library
The Exchange, Suite 245
270 Farmington Avenue
Farmington, CT 06032

Mr. Darl Hood
U.S. Nuclear Regulatory Commission
Office of Nuclear Reactor Regulation
Washington, D.C. 20555

Mr. P.K. Van Doorn
NRC Resident Inspector
McGuire Nuclear Station

8810070069 880927
PDR ADDCK 05000369
S PNU

JE22
/10