



Georgia Power

The Southern Electric System

P. D. Rice
Vice President
Vogtle Project

September 22, 1988

United States Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D. C. 20555

File: X7BG10
Log: GN-1492

Reference: Vogtle Electric Generating Plant - Unit 2
USNRC Inspection Report 50-425/88-19

The Georgia Power Company wishes to submit the following information concerning the violation in the referenced inspection report.

Violation 550-425/88-19-01, Failure to Follow Procedures, Resulting in Errors in Pipe Support QC and Design Documentation.

The Georgia Power Company (GPC) acknowledges the violation as identified in the USNRC report. This violation has been attributed to isolated human errors and failure to follow procedures due to procedure interpretation errors.

The errors were corrected by revising the drawings to reflect actual dimensions and to agree with the requirements of the Final Design Verification Program. A deviation report was written and was dispositioned to accept the support location as-is. The void Issue Ticket was deleted from the Process Package and the correct Issue Ticket was placed in the package.

To prevent recurrence, the Pullman Power Products Procedure X-24 was revised to require all redlined data, except fillet weld sizes, to be incorporated on the mylar. Engineering Supervision conducted a training session with all draftsmen on the requirements of Procedure X-24, with special emphasis on typical errors identified. Full compliance was achieved on July 19, 1988.

P. D. Rice
P. D. Rice

xc: USNRC - Region II
Suite 2900
101 Marietta St., N.W.
Atlanta, GA 30323

H. G. Baker, Jr.	D. R. Altman	C. W. Hayes
J. P. Kane	J. A. Bailey	R. W. McManus
R. H. Pinson	G. Bockhold, Jr.	Sr. Resident (NRC)
E. D. Groover	G. R. Frederick	D. H. Smith (OPC)
C. T. Moore	J. F. Swartzwelder	J. E. Joiner (TSLA)
R. A. Thomas	A. B. Gallant	NORMS

8810070231 880922
PDR ADOCK 05000425
Q PDC

IE01
10