October 5, 1988

MEMORANDUM FOR: Bruce A. Boger, Assistant Director for Region I Reactors Division of Reactor Projects 1/11

FROM: Walter R. Eutler, Director Project Directorate I-2 Division of Reactor Projects 1/11

SUBJECT: EXECUTIVE TEAM BRIEFING BY PD1-2

The plant review briefing for Dr. Murley and the Executive Team on the six plants assigned to PDI-2 is scheduled for Thursday, October 13, 1988 from 8:15 am to 10:30 am in Room 12-8-11.

The plants to be reviewed, in the order of presentation are: Hope Creek, Salem 182, Peach Bottom 283, Limerick 182, Susquehanna 182 and Shoreham.

Attached for your use are two copies of the briefing material.

B. Grimes J. Roe J. Taylor

E. Jordan

F. Gillespie

E. Weilzinger

M. Callahan

J. Wiggins

L. Plisco

151 Walter R. Butler, Director Project Directorate I-2 Division of Reactor Projects I/II

Attachment: As stated

cc w/attachment

T. Murley J. Sniezek F. Miraglia D. Crutchfield S. Varga G. Holahan E. Rossi L. Shao F. Congel

DISTRIBUTION

Central File NRC PDR Local PDR PDI-2 Reading GRivenbark DFischer

RMartin RClark MThadani SBrown MO'Brien

PDI-2/D WButler:mr 10/6/88



EDJR 5 FRE Lic



UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

October 5, 1988

MEMORANDUM FOR:

Eruce A. Boger, Assistant Director for Region I Reactors Division of Reactor Projects I/II

FRCM:

Walter P. Butler, Director Project Directorate I-2 Division of Reactor Projects I/II

SUBJECT: EXECUTIVE TEAM BRIEFING BY PDI-2

The plant review briefing for Dr. Murley and the Executive Team on the six plants assigned to PDI-2 is scheduled for Thursday, October 13, 1988 from 8:15 am to 10:30 am in Room 12-8-11.

The plants to be reviewed, in the order of presentation are: Hope Creek, Salem 182, Peach Bottom 283, Limerick 182, Susquehanna 182 and Shoreham.

Attached for your use are two copies of the briefing material.

Will R Buthe

Walt . Butler, Director Proje Directorate I=2 Division of Reactor Projects I/II

Attachment: As stated

cc w/attachment

T. Murley J. Sniezek F. Miraglia D. Crutchfield S. Varga G. Holahan E. Rossi L. Shao F. Congel

B. Grimes J. Roe J. Taylor E. Jordan F. Gillespie M. Callahan E. Wenzinger J. Wiggins

L. Plisco

PROJECTS BRIEFING FOR NRR EXECUTIVE TEAM BY PROJECT DIPECTORATE 1-2 DIVISION OF REACTOR PROJECTS 1/11

> HOPE CREEK SALEH 1&2 PEACH POTTOM 2&3 LIMERICK 1&2 SUSQUEHANNA 1&2 SHOREHAM

> > OCTOBER 13, 1987 OWFN: 12P11

PROJECT DIRECTORATE 1-2

DIRECTOR: SECRETARIES: LICENSING ASSISTANT: PROJECT ENGINEER WALTER BUTLER MONICA RUFFIN AND TONYA RUSSELL MARGARET (PEGGY) O'ERIEN DON FISCHER

PLANT	VENDOR CONTAINMEN'T	LEAD	ECT MANAGER BACKUP
HOPE CREEK PSE&G	GE Mark I	GEORGE RIVENBARK	STEWART BROWN
SALEM 182 PSE&G	W Large-dry	JIM STONE	Mchan Thadani
PEACH BOTTOM 283 PECC	GE Mark I	ROBERT MARTIN	RICHARD CLARK
LIMERICK 182 PECO	GE Mark II	RICHARD CLAPK	ROBERT MARTIN
Susquehanna 182 PP&L	CE Mark II	Mohan Thadani	JIM STONE
SHOREHAM	GE Mark II	STEWART BROWN	GEORGE RIVENPARK

HO<u>PE_CREEK</u> PLANT/LICENSEE_PERFORMANCE

OVERVIEW

. .

- * BWR 4 WITH MARK 1 CONTAINMENT
- SHARES SITE WITH SALEM 1 AND 2
- * ACHIEVED COMMERCIAL OPERATION 12/86
- CCMPLETED FIRST REFUELING ON APRIL 15, 1988
- SIGNIFICANT SEMIOR MANAGEMENT AND ORGANIZATIONAL CHANGES,

HOPE CREEK PERFORMANCE TREMPS SALP (MOST RECENT ENDED 1/15/88)

- 4 CATEGORY 1s: MAINTENANCE AND OUTAGE MANAGEMENT, EMERGENCY PREPAREDNESS, SECURITY AND SAFEGUARDS, TPAINING AND QUALIFICATION EFFECTIVENESS
- NO CATEGORY 3s

. .

.

- IMPROVED IN TRAINING AND CUALIFICATION EFFECTIVENESS
- DECLIMED IN LICENSING
- IMPROVING TREND IN RADIOLOGICAL CONTROLS AND CHEMISTRY AND IN ASSURANCE OF QUALITY

PEPFORMANCE INDICATORS

- * AVERAGE IN 1 AREA
- BELOW AVEPAGE IN 5 AREAS
- IMPPOVING TREND IN 5 AREAS
- * DECLINING TREND IN 2 AREAS

GENERAL

OVERALL
 PERFORMANCE
 IS IMPROVING

HOPE CPEEK LICENSING ACTIONS - STATUS ANTICIPATED LICENSING ACTIONS NEXT 12 MONTHS

IST PROGRAM

ċ.

. .

- * EAILEY SOLID STATE LOGIC MODULES
- GENERIC LETTER 87-09 TECH SPEC IMPROVEMENTS
- MSIV LEAKAGE
- DIESEL GENERATOR SURVEILLANCE INTERVAL
- * RPS & ECCS ACTUATION INSTR. SURVEILLANCE INTERVAL
- * REFUELING CRANE INTERLCCK
- ROD SEQUENCE CONTROL SYSTEM DELETION
- ROD WORTH MINIMIZER SETPOINT REDUCTION
- * WASTE PROCESSING CONTROL PROGRAM

HOPE CREEK LICENSING ACTIONS - STATUS (CONTINUED) ADECUACY OF PLANS/SCHEDULES

- OUTAGE PLANNING CONCEPNING SURVEILLANCES AND LICENSING ACTIONS NEEDS IMPROVEMENT
- OUTAGE FOR FIRST REFUELING CONDUCTED ESSENTIALLY AS SCHEDULED.
- DOES NOT HAVE INTEGRATED SCHEDULE

LICENSEE INITIATIVES

. .

- * FREQUENT TELEPHONE CONTACT
- * COMMITMENT TO IMPROVE QUALITY AND TIMELINESS OF SUBMITTALS

HOPE CREEK SUMMARY OVERVIEW

STRENGTHS

. .

- STRONG MANAGEMENT PRESENCE ONSITE
- CONMITMENT TO IMPROVE GUALITY
- GGRESSIVE, CONSERVATIVE APPROACH TO OUTSTANDING SAFETY CONCERNS
- LICENSED OPERATORS CONSERVATIVE AND SATETY CONSCIOUS ATTITUDE
- GOOD OPERATIONAL AWARENESS THROUGHOUT ORGANIZATION

WEAKNESSES

- * FREQUENCY OF PERSONNEL EPPOR IS RELATIVELY HIGH
- RECURRING EQUIPMENT ALIGNMENT PROBLEMS
- * NCN LICENSED OPERATORS LACK OF ATTENTION TO DETAIL DURING ROUTINE EVOLUTIONS

HOPE CREEK

CVEFALL ASSESSMENT

. .

0

0

- * PLANT OPERATED WELL DURING ITS FIRST FUEL CYCLE
- SUCCESSFUL FIPST REFUELING OUTAGE
- * LICENSEE MANAGEMENT PRO-ACTIVE AND RESPONSIVE TO OPERATING EXPERIENCE ISSUES
- * EFFECT OF SENIOR MAMAGEMENT CHANGES AND REORGANIZATION SHOULD BE MONITORED BY NRC
 - CONSIDEPABLE RESOURCES EXPENDED TO ENHANCE ALARA
 - CORRECTIVE ACTION TO ASSURE INCREASED NON-LICENSED OPERATOR ATTENTION TO DETAIL SHOULD BE MONITORED BY NRC
 - EFFORTS ARE BEING MADE TO STANDARDIZE PROGRAMS AND PROCEDURES AT HOPE CREEK AND SALEM
 - LICENSEE MANPOWEP/EFFICIENCY REVIEW SHOULD BE MONITORED BY NRC

HOPE CREEK PLANT/LICENSEE PERFORMANCE

PLANT PERSONNEL OVERVIEW

. .

- * 5 OPERATING SHIFTS/8-HOUR SHIFT OPERATION
- * WILL PROBAPLY GO TO 12-HOUR SHIFTS
- LICENSED OPERATORS ON PLANT STAFF 4 SROs, 2 ROS
- 24 LICENSED OPERATORS ON SHIFT DUTIES 15 SROs, 9 ROS
- ° 6 STAS ALL DEGREED 5 SROS
- * TRAINING PROGRAMS NOT YET ACCREDITED BY INPO

MAJOR OPERATING EVENTS

FIRST REFUELING OUTAGE (52 DAYS DURATION)
 SUCCESSFULLY COMPLETED ON APRIL 15, 1988.

4

HOPE CREEK

PLANT/LICENSEE PERFORMANCE (CONTINUED)

PERFORMANCE INDICATOR OVERVIEW

TRENDS: PLANT DATA LAST 2 CUARTERS THRU SECOND QUARTER OF 1988 RELATIVE TO THE PREVIOUS 4 CUARTERS

DEVIATIONS: PLANT DATA PELATIVE TO INDUSTRY DATA LAST 4 QUARTERS THRU SECOND QUARTER OF 1988

INDICATOR	TREND	DEVIATION FROM OLDER PLANTS
AUTO SCRAMS TOTAL	I	В
AFETY SYSTEM ACTUATIONS	I	P
FREQUENCY	1	В
FAILURES	D	В
ORCED OUTAGE RATE	1	
EQUIPMENT FOPCED OUTAGES	D	В

I = IMPROVED A = ABOVE AVERAGE D = DECLINED B = BELOW AVERAGE

HOPE CREEK

PLANT/LICENSEE PERFORMANCE (CONTINUED)

SPECIAL LICENSING ACTIONS (JUNE 1987 TO PRESENT)

TWO CODE RELIEFS

. .

- ONE APPENDIX J EXEMPTION
- ONE EMERGENCY TS CHANGE
- NO DISCRETICMARY ENFORCEMENTS/TEMPORARY WAIVERS OF COMPLIANCE

SIGNIFICANT PERFORMANCE IMPROVEMENT PROGRAMS UNDERWAY OR PLANNED

- * RELIABILITY CENTER MAINTENANCE PROGRAM (UNDERWAY)
- INPO HUMAN PERFORMANCE EVALUATION SYSTEM (JUST BEGINNING)
- ISLAND WIDE WOPK CONTROL PROGRAM (UNDERWAY)
- * PRA STUDY (INITIATE IN SEPT, 88)
- CONFIGURATION BASELINE PROGRAM (START EARLY 1989)
- SAFETY SYSTEM FUNCTIONAL REVIEWS (UNDERWAY)

INSPECTION FINDINGS

INSPECTIONS CONDUCTED (JUNE 1, 1987 TO MARCH 21, 1988)

* 22 FOUTINE INSPECTIONS

VIOLATIONS

. *

- * NO ESCALATED ENFORCEMENT
- 9 LEVEL IV
- ° 1 LEVEL V

ALLEGATIONS

NO OPEN AL EGATIONS

. .

LICENSING ACTIONS - STATUS

BACKLOG OVERVIEW

LAST BRIEFING	(6/11/87)	CURRENT (10/01/	88)		ADDED	CO	MPLETED
18		18			21		21
					CAT :	1 CAT 2	CAT 3
AMENDMENT	PEQUESTS	RECEIVED	AFTER	9/4/87	0	5	3
AMENDMENT COMPLETED	PECUESTS BY PM	RECEIVED	AFTER	9/4/87	0	3	С
AMENDMENT	REQUESTS BY PM (6)	RECEIVED /4/87 TO	PRIOR	TO 9/4	/87		4

HOPE CREEK LICENSING ACTIONS - STATUS (CONTINUED) MAJOP CURRENT ISSUES IN PROGRESS

IST PROGRAM

. . .

* EAILEY SOLID STATE MODULES

MAJOR PLANT SPECIFIC ISSUES COMPLETED (JUNE 1987-PRESENT)

- ATWS SLC SYSTEM
- * PURGE VALVE OPERABILITY
- * INSERVICE INSPECTION PROGRAM
- LOCAL LEAK RATE TEST EXEMPTION

MAJOR GENERIC ISSUES

ATWS COMPLETE

. . .

HOPE CREEK 1 NUCLEAR GENERATING STATION

SALP SUMMARY					
PERIOD ENDING	10/85	10/86	01/88		
PLANT OPERATIONS	-	2	2		
RADIOLOGICAL CONTROLS AND CHEMISTRY	2	2	2		
MAINTENANCE AND OUTAGE MANAGEMENT	2	1	1		
SURVEILLANCE		2	2		
EMERGENCY PREP.	2	1	1		
SECURITY & SAFEG.	1	1	1		
ENGINEERING SUPPORT		- 1, 1	2		
LICENSING ACTIVITIES	2	1	2		
ASSURANCE OF QUALITY	1	2	2		
TRAINING & QUALIFICATION EFFECTIVENESS	-	2	1		

SALEM 1 AND 2 PLANT/LICENSEE PERFORMANCE

OVERVIEW

• . •

- * FOUR LOOP M PWR
- SHARED SITE WITH HOPE CREEK
- BORCN INJECTION TANK REMOVED (UNIT 1)
- NEW VP NUCLEAR
- * OVEPALL PERFORMANCE CONTINUES TO IMPROVE
- * NUCLEAR DEFARTMENT COMPLETED MANPOWER/EFFICIENCY PEVIEW
- INITIATED A PLANT SYSTEM DESIGN BASIS DOCUMENTATION PROGRAM
- * LEVEL III VICLATION (\$50K CIVIL PEMALTY) ISSUED FOR FIRE PROTECTION DEFICIENCIES
- * EFFORTS TO STANDARDIZE PROGRAMS AND PROCEDURES AT ALL LICENSEE FACILITIES

SALEM 1 AND 2

PERFORMANCE TREMDS

SALP (MOST RECENT ENDED 12/31/87)

- 5 CATEGORY 1s: MAINTENANCE, EMERGENCY PPEPAPEDNESS, REFUELING OUTAGE MANAGEMENT, ASSURANCE OF GUALITY, SECURITY AND SAFEGUARDS
- NO CATECOPY 3
- CHEMISTRY AN' PADIOLOGICAL CONTROLS ONLY AREA TO DECLINE
- IMPROVED IN REFUELING OUTAGE MANAGEMENT, ASSURANCE OF QUALITY

PERFORMANCE INDICATORS (DATA THROUGH 06/30/88)

UNIT 1

. .

- ABOVE AVERAGE PERFORMANCE IN 3 APEAS
- * BELOW AVERAGE PERFORMANCE IN 3 AREAS
- * IMPROVING TRENDS IN 3 OF 6 APEAS

UNIT 2

- ABOVE AVERAGE PERFORMANCE IN 2 AREAS
- * EELOW AVERAGE PERFORMANCE IN 4 AREAS
- * IMPROVING TRENDS IN 2 OF 6 APEAS

EALEM, UNIT 1 AND 2 PERFORMANCE TPENDS (CONTINUED)

GENERAL

. .

- WEAKNESSES IN INTERFACE WITH DESIGN ENGINEERING, OPERATOR REQUALIFICATION PROGRAM, AND ATTENTION TO DETAIL DURING SUPVEILLANCE TESTING
- IMPROVED PLANT TRIP FATE SUCCESSFUL TRIP REDUCTION PROGRAM.

SALEM 1 AND 2 LICENSING ACTIONS - STATUS

ANTICIPATED LICENSING ACTIONS NEXT 12 MONTHS

- Ho ANALYZER ACTION LONGER ANALYZEP INOPERABILITY
- PHP FLOW REQUIREMENTS
- CONTAINMENT ISOLATION VALVES REVISES LIST OF ISOLATION VALVES
- * TUPBINE BYPASS VALVE TESTING EXTENDS TEST INTERVAL
- DIESEL GENERATOR TESTING REDUCES TEST REQUIREMENTS
- CONTAINMENT AIPLOCKS TESTING OF AIRLOCK SEALS
- POPS INOPERABLE CHANGES ACTION STATEMENT
- SNUBBER TAPLE REMOVES SNUBBER TABLE
- * APPENDIX B REMOVES APPENDIX B FROM TS
- * LICENSE EXTENSIONS
- RELAX REGUIREMENTS ON MODE CHANGES
- SEA TURTLE IMPINGEMENTS

SALEM

LICENSING ACTIONS - STATUS (CONTINUED)

ADEQUACY OF PLANS/SCHEDULES

- OUTAGE ACTIVITIES PLANNING GOOD
- MANAGEMENT AND PLANNING DEPARTMENT ARE AGGRESSIVE IN PREPLANNING OUTAGES
- DUPING OUTAGES, THEY ARE EQUALLY AGGRESSIVE IN SEEING THAT WORK IS SATISFACTORILY PERFORMED
- OUTAGE LICENSING PLANNING GOOD SOME IMPROVEMENT
 CONCERNING RELIEF FLANNING IS NECESSARY

LICEMSEE INITIATIVES

MONTHLY LICENSING STATUS MEETINGS HELD

ź

- FREQUENT TELEPHONE CONTACT
- SOME WEAKNESSES IN SCHEDULAR PLANNING OF CHANGE REQUESTS

SALEM UNITS 1 AND 2 SUMMARY OVERVIEW

STRENGTHS

- RECOGNITION OF WEAKNESSES AND A PRO-ACTIVE PROGRAM TO ADDRESS WEAKNESSES
 EXAMPLE;
 - 1. MAJOR REBUILDING OF DESIGN BASIS DOCUMENTATION
 - 2. FIRE PROTECTION UP-GPADE PROGRAM
 - ENVIRONMENTAL PROTECTION UP-GRADE PROGRAM
 - 4. SERVICE WATER SYSTEM ACTION PLAN (A DEDICATED PROJECT TEAM WAS FORMED)
- RELIABILITY CENTERED MAINTENANCE PROGRAM
- PLANNED PRA FOR SALEM
- MANAGED MAINTENANCE INFORMATION SYSTEM (ELECTRONIC DATA BASE SYSTEM TO TRACK WORK ORDERS, ETC.)
- * TRIP REDUCTION PROGPAM WITH WOG
- MAJOR REORGANIZATION TO STRENGTHEN CORE GROUP ENGINEERING EXPERTISE.

SALEM, UNITS 1 AND 2

VEAKNESSES

. . .

- * LICENSING/DESIGN BASIS DOCUMENTATION SOMETIMES NOT COORDINATED (EXAMPLE: ELECTRICAL "BREAKER COORDINATION")
- * SERVICE WATER SYSTEM (CORROSION/EROSION PROBLEMS)
- SCHEDULING OF REGULATORY ACTIONS (EXAMPLE: LATE SUBMITTAL FOR RTD MODS DURING REFUELING - LATE ISI PROGRAM)
- INCONSISTENT OUTAGE PERFORMANCE (I.E., VERY SHORT PREVIOUS OUTAGE THEN LENGTHY OUTAGE THIS TIME)

OVERALL ASSESSMENT

- * MANAGED MAINTENANCE PROGRAM HAS RESULTED IN REDUCING WORK ORDERS
- * EXCELLENT HOUSEKEEPING
- MANAGEMENT REORGANIZATION IS YIELDING INCREASED MANAGEMENT INVOLVEMENT
- PLANT OPERATIONS TRENDING UPWARDS

1.00

SALEM 1 AND 2 PLANT/LICENSEE PERFORMANCE

PLANT PERSONNEL OVERVIEW

. .

- * 5 OPERATING SHIFTS/8 HOUR SHIFT OPERATION
- CONSIDERING GOING TO 12-HOUR SHIFTS
- * LICENSED OPERATOPS ON PLANT STAFF 8 SPOS
- SE LICENSED OPERATORS ON SHIFT DUTIES 15 SROs, 20 POs
- * 11 STAS ALL DEGREED ALL SROS
- * 10 TRAINING PROGRAMS ACCPEDITED BY INPO

MAJOR OPERATING EVENTS

- PRIMARY SYSTEM LEAK THROUGH CANOPY SEAL WELD
- * BREAKER CCORDINATION

SALEM 1 AND 2

PLANT/LICENSEE PERFORMANCE (CONTINUED)

PEPFORMANCE INDICATOR OVERVIEW

TRENDS: PLANT DATA LAST 2 QUARTERS ENDING SECOND QUAPTER OF 1988 RELATIVE TO THE PREVIOUS 4 QUAPTERS DEVIATIONS: PLANT DATA RELATIVE TO INDUSTRY DATA LAST 4 QUARTERS (DATA THROUGH THE SECOND QUARTER OF 1988 INCLUDED)

SALEM UNIT 1 INDICATOR	TREND	DEVIATION
AUTO SCRAMS TOTAL	D	A
SAFETY SYSTEM ACTUATIONS	c	A
SIGNIFICANT EVENT FRECUENCY		E
SAFETY SYSTEM FAILURES	1	В
FORCED CUTAGE RATE	1	A
EQUIPMENT FORCED OUTAGES	D	В

A = ABOVE AVERAGE B = BELOW AVERAGE

D = DECLINED -- = NO CHANGE

SALEM J AND 2

PLANT/LICENSEE PEPFORMANCE (CONTINUED)

PERFORMANCE INDICATOR OVERVIEW

TRENDS: PLANT DATA LAST 2 CUARTERS ENDING SECOND CUARTER OF 1988 RELATIVE TO THE PREVIOUS 4 QUARTERS DEVIATIONS: PLANT DATA RELATIVE TO INDUSTRY DATA LAST 4 QUARTERS (DATA THROUGH THE SECOND QUARTER OF 1988 INCLUDED)

SALEM UNIT 2		an that a set
INDICATOR	TREND	DEVIATION
AUTO SCRAMS TOTAL	D	В
SAFELY SYSTEM ACTUATIONS	D	A
SIGNIFICANT EVENT FREQUENCY		В
SAFETY SYSTEM FAILURES	I	В
FORCED OUTAGE PATE	1	4
EQUIPMENT FORCED OUTAGES	D	Р

I = IMPROVED A = ABOVE AVERAGE D = DECLINED B = BELCY AVERAGE

SALEM 1 AND 2

PLANT/LICENSEE PERFORMANCE (CONTINUED)

SPECIAL LICENSING ACTIONS (JUNE 1987 TO PRESENT)

- * ONE CODE FALIEF WELD OVERLAYS
- * ONE EMERGENCY TS CHANGE WITH A TEMPORARY WAIVER OF COMPLIANCE

SIGNIFICANT PERFORMANCE IMPROVEMENT PROGRAMS UNDERWAY OR PLANNED

- * RELIABILITY CENTER MAINTENANCE PROGRAM (UNDER.AY)
- ISLAND WIDE WORK CONTROL PROGRAM (UNDERWAY)
 - PRA STUDY

· · ·

SAFETY SYSTEM FUNCTIONAL REVIEWS (IN PROGRESS)

1

INSPECTION FINDINGS

INSPECTIONS CONDUCTED (JUNE 1, 1988 TO JUNE 29, 1988)

33 ROUTINE INSPECTIONS (UNIT 1) 31 ROUTINE INSPECTIONS (UNIT 2)

VIOLATIONS

1. 1

· 4 LEVEL IV

ALLEGATIONS

NO OPEN ALLEGATIONS

· · · · ·

1.11

LICENSING ACTIONS - STATUS BACKLOG OVERVIEW

LAST BRIEFING	(6/11/87)	CURRENT (7/01/88)	ADDED	COMP	PLETED
UNIT 1	200 M	<u>41</u>	20 21	17 18	
			CAT 1	CAT 2	CAT 3
AMENDMENT	RECUESTS	PECEIVED AFTER 9/4/8 (EACH UNIT)		CAT 2 5	CAT 3 4
		RECEIVED AFTER 9/4/8 (EACH UNIT) RECEIVED AFTER 9/4/8 (EACH UNIT)	7 0		CAT 3 4 C

SALEM 1 AND 2

LICENSING ACTIONS - STATUS (CONTINUED)

MAJOR CURRENT ISSUES IN PROGRESS

. . . .

- CONTAINMENT ISOLATION VALVE (TEST LIST)
- * TURBINE BYPASS VALVE TEST INTERVAL EXTENSION
- CONTAINMENT AIRLOCKS SEAL TESTING
- * SEA TURTLE IMPINGEMENT ON TRASH BARS

MAJOR PLANT SPECIFIC ISSUES COMPLETED (JUNE 1987-PRESENT)

- * RTD BYPASS SYSTEM MCDIFICATIONS
- INCREASE BORON CONCENTRATION IN RWST AND ACCUMULATORS

MAJOR GENERIC ISSUES

- CLOSURE OF MPA B-96
- CLOSURE OF MPA B-96 STEAM BINDING OF AFW PUMPS," GENERIC LETTER 88-03

1.1

SALEM 1 AND 2 GENERATING STATION

	SALP SUMMARY		
PERIOD ENDING	09785	09/86	12/87
PLANT OPERATIONS	2	2	2
RADIOLOGICAL CONTROLS	1	1	2
MAINTENANCE	2	1.	1
SURVEILLANCE	2	2	2
FIRE PROTECTION	2	N/A	N/A
EMERGENCY PREP.	2	1	1
SECURITY & SAFEC.	1	1 .	1
OUTAGES	2	2	1
ASSURANCE OF QUALITY	N/A	2	1
ENGINEEPING SUPPORT	N/A	2	2
LICENSING	2	2	2
TRAINING & GUALITY EFFECTIVENESS	N/A	2	2

PEACH ECTTOM ATOMIC POWER STATION UNITS 2 AND 3 PLANT/LICENSEE PERFORMANCE

OVERVIEW

1 1

- * BWR 4/MARK I
- DUAL UNIT SITE
- * SHUTDOWN SINCE 3/31/87
- * COFRECTIVE ACTION PLAN FOR SHUTDOWN ISSUES
- * NEW MANAGEMENT

ACTIONS FCP PESTAPT:

- * ENFORCEMENT ACTIONS
- REVIEW OF PLAN FOR PESTART
- * LICEMSEE READINESS
- * INSPECTIONS
- PUBLIC & STATE INVOLVEMENT
- * ERIEFINGS
- * DECISION
- * STARTUP MONITORING

PEACH ECTTOM ATOMIC POWER STATION PERFORMANCE TRENDS

SALP (MOST PECENT ENDED 05/31/87)

- * 2 RATINGS OF UNACCEPTABLE: OPERATIONS, GUALITY ASSURANCE
- * 1 NOT FATED: TPAINING AND GUALIFICATION EFFECTIVENESS
- 7 CATEGORY 2: RAD CONTROLS, MAINT., SURVEILLANCE, EP, SECUPITY, TECH SUPPORT, LICENSING
- CATEGORY 3: FIRE PRUTECTION AND HOUSEKEEPING

PERFORMANCE INDICATOR TRENDS

BOTH UNITS HAVE BEEN SHUTDOWN SINCE 3/31/87

GENERAL

DETERMINATION OF OPERATING PERFORMANCE TRENDS IS PREMATURE

PEACH BOTTOM ATOMIC POWER STATION LICENSING ACTIONS - STATUS

ANTICIPATED LICENSING ACTIONS NEXT 12 MONTHS

- * PIPING REPLACEMENT TS MODS AND ELIMINATION OF REACTOR HEAD SPPAY PIPING
- UNIT 3 RELOAD AMENDMENT
- DIESEL GENERATOR CARDOX
- * REMOVAL OF CAPDOX FROM CONTROL ROOM
- * UNDERVOLTAGE PROTECTION MODIFICATIONS
- * MINIMUM SPM COUNTRATE
- * SECOND 10-YEAR IST PROGRAM
- OVERTIME LIMIT TECH SFEC
- RELOAD TOPICAL REPORTS
- STATION BLACKOUT RULE
- * NONCONFORMING PIPING MATERIALS
- CORRECTION OF ERRORS FOR UNIT 2 RELOAD TS
- * 50.62 ATWS TS

PEACH BOTTOM ATOMIC POWER STATION LICENSING ACTIONS - STATUS (CONTINUED)

ANTICIPATED ACTIONS-CONTINUED

- * CONTAIN ISOLATION DEPENDABILITY, II.E.4.2(7)
- SALEM ATWS (3 ITEMS)

. .

- APP J CONTAIN LEAK TESTING EXEMPTION
- EMERGENCY SERVICE WATER LCO

ADEQUACY OF PLANS/SCHEDULES

 INITIAL LICENSEE PLANS AND SCHEDULES FOR COPPECTIVE ACTION WERE EXTENDED CONSIDERABLY AS THE SCOPE OF THE PROBLEMS WERE REALIZED.

LICENSEE INITIATIVES

- * PLAN FOR PESTART
 - NEW MANAGEMENT
 - CPERATOR TRAINING
 - ADDITIONAL STAFFING
 - HIGHER STANDARDS

PEACH BOTTOM ATOMIC POWER STATION SUMMARY OVERVIEW

STRENGTHS

. .

- NEW MANACEMENT
- * PLAN FOR RESTART
- STRONG ENGINEERING SUPPORT
- SINCEPE EFFORTS AND PROGRESS SHOWN IN IMPROVEMENTS IN MANAGEMENT ATTITUDES, OPERATOR ATTITUDE TRAINING AND PROFESSIONALISM, HOUSEKEEPING, PLANT LABELING, DECONTAMINATION, MAINTENANCE BACKLOG AND COMMUNICATIONS WITH STATE AND LOCAL COVERNMENTS
- STATUS OF MAINTENANCE

WEAKNESSES

AS CF C3/31/87

- CORPORATE MANAGEMENT FAILED TO RECOGNIZE AND CORRECT PROBLEMS
- * PLANT MANAGEMENT LEADERSHIP AND SKILLS
- LICENSED OPERATOR PEPLACEMENT PROGRAM
- CULTUPE

PEACH ECTTOM ATOMIC POWER STATION

CURRENT

. .

- SECURITY
- OPERATIONS TRAIMING

OVERALL ASSESSMENT

- IMPACT OF EXECUTIVE VP NUCLEAR IS POSITIVE
- PLANT MANAGER CESEPVED TO HAVE POSITIVE EFFECT ON PLANT STAFF
- HOUSEKEEPING IMPROVED
- REDUCTION OF CONTAMINATED AREAS
- LABELING OF SYSTEMS, COMPONENTS GPEATLY IMPROVED
- SECURITY AND OPERATIONS TRAINING TO GET CONTINUED ATTENTION
- PROGRAM APPEARS TO BE GOING IN RIGHT DIRECTION

PEACH BOTTOM ATOMIC POWER STATION

LICENSE AMENDMENT APPLICATIONS/EXEMPTION REQUESTS EXPECTED TO BE FILED DURING THE NEXT TWELVE MONTHS

DELETE ORGANIZATION CHAPTS (GL 88-06) ISEG RSCS/RWM OPERABILITY PEQUIREMENTS MODIFY ISOLATION VALVE STPOKE TIMES APRM TRIP SETPOINT CHANGE CLARIFICATION OF POIS/ECCS TRIP LOGIC AUGMENTED ISI (GL 88-01) DIESEL GENERATOF MAINTENANCE FREQUENCY RPS TESTIMO FREQUENCY ECCS/D-G ACCELERATED TESTING PELIEF MSIV LOW PRESSURE ISOLATION SETPOINT CHAMGE

.

PEACH BOTTOM ATOMIC POWER STATION PLANT/LICENSEE PERFORMANCE

PLANT PERSONNEL OVERVIEW

- STAFFING LEVELS INCREASING
- 6 SHIFTS/8 HOUR SHIFTS/CLOCKWISE ROTATION
- * 16 LICENSED OPERATORS ON PLANT STAFF
- 36 LICENSED OPERATORS ON SHIFT DUTIES 16 SROs, 20 RC
- CUPPENT TOTAL 18 52, TO RISE TO 75 BY NOV. 1989
- SRO/PCs IN TRAINING 8 SROs, 8 ROS

MAJOR EVENTS

NO MAJOR OPERATIONAL EVENTS SINCE THE SHUTDOWN OF MARCH 31, 1987

. .

PEACH BOTTOM ATOMIC POWER STATION 2&3 PLANT/LICENSEE PERFORMANCE (CONTINUED)

TRENDS: PLANT DATA LAST 2 CUARTERS RELATIVE TO THE PREVIOUS 4 QUARTERS DEVIATIONS: PLANT DATA RELATIVE TO INDUSTRY DATA LAST 4 QUARTERS (DATA THROUGH THE FIRST QUARTER OF 1988 INCLUDED)

INDICATOR	UNITS 2 AND 3	DEVIATIONS UNITS 2 AND 3
AUTO SCRAMS TOTAL SAFETY SYSTEM ACTUATIONS	(PLANT HAS PEE	N SHUTDOWN SINCE
SIGNIFICANT EVENT FREQUENCY SAFETY SYSTEM FAILURES FORCED CUTAGE RATE EQUIPMENT FORCED CUTAGES	3/31	N SHUTDOWN SINCE
I = IMPROVED D = DECLINED = NO CHANGE	A = ABOVI B = BELO	E AVERAGE W AVERAGE

PEACH BOITOM ATOMIC POWER STATION PLANT/LICENSEE PERFORMANCE (CONTINUED)

SPECIAL LICENSING ACTIONS (JUNE 1987 TO PRESENT)

- TECH SPEC ORGANIZATIONAL STRUCTURE CHANGE
- * REGULATORY EFFECTIVENESS REVIEW
- HYDROGEN WATER CHEMISTRY REVIEW
- DIESEL GENERATOR FUEL CIL
- * 10 CPR 50,62 ATWS

. .

SIGNIFICANT PERFORMANCE IMPROVEMENT PROGRAMS UNDERWAY OR PLANNED PLAN FOR RESTART

- CHANGE OFGAMIZATIONAL STRUCTURE
- DEVELOP MANAGEMENT SYSTEMS AND MANAGERIAL SKILLS
- STPENGTHEN THE INDEPENDANT ASSESSMENT PROCESS
- ESTABLISH A FLANT MANAGEMENT TEAM WITH ENHANCED RESOURCES AND SKILLS
- DEVELOP LICENSED OPERATOR RESOURCES
- COMMUNICATE EXPECTATIONS AND PROVIDE TRAINING AND OTHER SUPPORT TO PECO EMPLOYEES

PEACH BOTTOM ATOMIC POWER STATION INSPECTION FINDINGS (BY REGION I)

INSPECTIONS CONDUCTED (MARCH 1987 TO PRESENT)

- 14 ROUTINE INSPECTIONS
- * 26 SPECIAL INSPECTIONS:

VIOLATIONS

.

- 1 ESCALATED ENFORCEMENT(ACTIONS PENDING)
- ° _ 21 LEVEL III AND IV

ALLEGATIONS(6/22/88)

11/7 OPEN ALLEGATIONS

1

LICENSING ACTIONS - STATUS

BACKLOG OVERVIEW

LAST BRIEFING (10/06/87) (7/21/88)		ADDED		CCMPLETED			
42/40		30/25		12/6		24/21	
					CAT 1	CAT 2	CAT 3
AMENDMENT	REQUESTS	RECEIVED	AFTER	9/4/87	0/0	3/3	2/0
AMENDMENT	PECUESTS DY PM	PECEIVED	AFTER	9/4/87	0/0	0/0	0/0
AMENDMENT	RECUESTS BY PM	RECEIVED	PRIOR	TO 9/4/87	0/0	0/0	0/0

PEACH BOTTOM ATOMIC POWER STATION LICENSING ACTIONS - STATUS (CONTINUED)

MAJOR CURPENT ISSUES IN PROGRESS

* SER CM PESTART PLAN

. 8

- * DIESEL GENERATOR CAPDOX
- * CONTROL POOM CARDOX
- MINIMUM SPM COUNTRATE
- DEGRADED VOLTAGE PROTECTION
- SECOND TEN YEAR ISI PROCRAM
- * UNIT 3 RELOAD
- * ISEG AND OVERTIME CONTROLS
- * PIPING REPLACEMENT TS AND HEAD SPRAY REMOVAL
- IAT INSPECTION

PEACH POTTOM ATOMIC POWER STATION LICENSING ACTIONS - STATUS (CONTINUED)

MAJOR PLANT SPECIFIC ISSUES COMPLETED (JUNE 1987 - PRESENT)

- HYDROGEN WATER CHEMISTRY REVIEW
- * OPERATOR HUMAN FACTORS TRAINING
- ORGANIZATIONAL STRUCTURE TS REVISION
- * UNIT 2 RELOAD

1.1

- DIESEL GENERATOP FUEL CIL REQUIREMENTS
- \$ 50,62 ATWS SEP
- * MAINTENANCE TEAM INSPECTION
- EOP TEAM INSPECTION

PM/REGION I ISSUE INTERACTION

- IR 86-25 LCO ON ESW PUMPS
- IR 87-13 THREE FIRE PROTECTION ITEMS
- IR 88-13 SHUTDOWN COOLING ISOLATION

PEACH BOTTOM ATOMIC POWER STATION LICENSING ACTIONS - STATUS (CONTINUED)

ISSUES RECEIVING MINIMAL CUPPENT ATTENTION

- * FG 1.97 INSTRUMENTATION
- * SALEM ATWS (3 ITENS)
- * DCPDR
- * SPDS
- FIRE PROTECTION PPCGRAM.
- * FIRE DARRIERS
- * RELOAD TOPICALS

MAJOR GENERIC ISSUES

- * NUPEG-0737 ITENS COMPLETE EXCEPT FOR: CONTAINMENT ISOLATION DEPENDABILITY, II.E.4.2(7)
- NUREG-0737 SUPPLEMENT 1 ITEMS COMPLETE EXCEPT FOF: REGULATORY GUIDE 1.97 SPDS DCRDE FOLLOW UP
- OTHER MPAS COMPLETE EXCEPT FOR: SALEM ATWS, THREE PAPTS F-99 OVERTIME LIMIT TS

LIMERICK, UNITS J AND 2 PLANT/LICENSEE PERFORMANCE

OVERVIEW

- GE BWR 4s WITH MARK II CONTAINMENTS
- LOCATED ON SCHUYLKILL RIVER, 1.7 MILES SE OF POTTSTOWN, PA.
- * MAJOR REORGANIZATION OF ON-SITE STAFF IN FEBRUARY 1988
- UNIT 1 CPEFATING SINCE AUGUST 1985
- * UNIT 2 FUEL LCAD TARGETED FOR JUNE 1, 1989; SYSTEM TESTING AND TURNOVER FURNING AHEAD OF SCHEDULE
 - ANNUAL FULL PARTICIPATION EMERGENCY EXERCISE CONDUCTED APRIL 5, 1988 WITH FULLY SATISFACTORY RESULTS
 - ALL COMPONENTS OF POINT PLEASANT DIVERSION PROJECT UNDER CONSTRUCTION

LIMERICK, UNITS 1 AND 2 PERFORMANCE TRENDS

UNIT 1 SALP (MOST PECENT ENDED 4/30/88)

- * E CATEGORY 1s: PLANT OPERATIONS, RADIOLOGICAL CONTPOLS, MAINTENANCE, SURVEILLANCE, SECURITY AND SAFETY ASSESSMENT/ CUALITY VERIFICATION
- 2 CATEGORY 2s: EMERGENCY PREPAREDNESS AND ENGINEERING/TECHNICAL SUPPORT.
- NO CATEGORY 3s

UNIT 2 SALP (MOST RECENT ENDED 7/31/87)

- * 7 CATEGORY 1s: CONTAINMENT, SAFETY-RELATED STRUCTURES AND MAJOR STEEL SUPPORTS, SOILS & FOUNDATIONS, PIPING SYSTEMS AND SUPPORTS, SAFETY-PELATED COMPONENTS-MECHANICAL, AUXILARY SYSTEMS, ELECTRICAL EQUIPMENT AND CABLE, INSTRUMENTATION AND CONTROL SYSTEMS AND LICENSING ACTIVITIES
- CATEGORY 2s: ENGINEERING AND ASSURANCE OF QUALITY

NO CATEGORY 3s

φ.

LIMERICK, UNITS 1 AND 2 PERFORMANCE TRENDS (CONTINUED)

PERFORMANCE INDICATIONS-UNIT 1 (DATA THROUGH 06/30/88)

- DEVIATION FROM CLDER PLANTS: APOVE AVERAGE IN THREE INDICATORS, PELOW AVERAGE IN THREE INDICATORS
- IMPPOVING TREND IN FOUR INDICATORS; DECLINING TREND IN ONE

GENERAL

- * VERY COOD SALP SCORES; ONE OF BEST IN REGION
- * PERFORMANCE OF UNIT 1 HAS BEEN ABOVE AVERAGE

LIMERICK, UNITS 1 AND 2 LICENSING ACTIONS - STATUS

ANTICIPATED LICENSING ACTIONS NEXT 12 MONTHS

- ACTIONS TO BE SUBMITTED IN SUPPORT OF NEXT REFUELING OUTAGE (CONMENCING JANUARY 14, 1989)
 CORE RELOAD ANALYSES
 - FOUR AMENDMENTS TO SUPPORT MODIFICATIONS BEING MADE DURING CUTAGE

FOUR AMENDMENTS TO SUPPORT UNIT 2 COMMON SYSTEMS TIE-INS FOUR AMENDMENTS TO CORRECT PROBLEMS

- COMPLETION OF REMAINING 4 MPAs (IST, THREE SALEM ATWS ISSUES)
- UNIT 2 TSs
- * MULTIPLE TEAM INSPECTIONS OF UNIT 2 IDCA PROGRAM

ADECUACY OF PLANS/SCHEDULES

- MONTHLY STATUS MEETING WITH PROJECT MANAGER.
- * FREQUENT TELEPHONE CONTACT WITH PROJECT MANAGER
- COMMITMENT TRACKING SYSTEM.
- LICENSEE WELL-PREPARED FOR TECHNICAL MEETINGS

LIMERICK, UNITS 1 AND 2 SUMMARY OVERVIEW

STPENGTHS

- * EXCEPTIONAL SITE MANAGEMENT AND SUPERVISION PPOVIDE LEADEARSHIP TO SUPPORT CONTINUED STRONG PERFORMANCE, GOOD MGRALE AND STRONG SAFETY PERSPECTIVE.
- STRONG ORIENTATION TOWARD SAFE PLANT OPERATION BY OPERATORS EXCELLENT LICENSED OPERATOR ATTITUDES.
- GCOD WORK ON DRUG ALLEGATIONS AND FITNESS FOR DUTY. MANDATORY ROUTINE DRUG TESTING PROGRAM
- * GCCD ABILITY TO PROACTIVELY IDENTIFY/PREDICT PROBLEMS, CRITICALLY SELF-EVALUATE PERFORMANCE AND TAKE EFFECTIVE CORRECTIVE ACTIONS.
- STRONG CA/CC ORGANIZATION AND PROGRAMS
- STRONG EMPHASIS ON HOUSEKEEPING AND COLOR-CODING AND IDENTIFICATION OF ALL SYSTEMS AND COMPONENTS

WEAKNESSES

- * ENGINEEPING SUPPORT FOR OPERATIONS STRAINED DUE TO DEMANDS FOR PEACH BOTTOM AND LIMERICK 2 CONSTRUCTION. LICENSEE TAKING ACTIONS TO CORRECT.
- INADEGUATE ATTENTION TO WATER CHEMISTRY AND CORROSION
 CONTROL HAS RESULTED IN MULTIPLE FUEL FAILURES

LIMERICK, UNITS 1 AND 2 SUMMARY OVERVIEW (CONTINUED)

CVERALL ASSESSMENT

- VERY GOOD SALP SCORES; ONE OF THE BEST IN THE REGION
- * FUEL FAILURES WILL RESTRICT POWER GENERATION TO ABOUT 65% UNTIL SCHEDULED REFUELING (JAN, '89) AND MAY CAUSE EARLIER SHUTCONN
- NO SCRAMS IN PAST YEARS; NO SIGNIFICANT LERS
 NO FORCED OUTAGES AND NO SAFETY SYSTEM FAILURES

LINEPICK UNIT 1 PLANT/LICENSEE PERFORMANCE

MAJOR OPERATING EVENTS

. .

- DURING STARTUP FROM REFUELING OUTAGE (SEPT. 1987), PLANT TRIP FROM 83%
 POWER AS A RESULT OF CLOSURE OF TURBINE STOP VALVES DUE TO
 HIGH LEVEL IN MOISTURE SEPARATOR.
- * AUTOMATIC SCRAM FROM 90% POWER (SEPT. 1987) DUE TO MAIN TURBINE TRIP CAUSED BY FAILUPE OF WELD IN ELECTROHYDRAULIC CONTROL SYSTEM.
- * PLANT OPERATED CONTINUOUSLY (195 DAYS) FROM SEPTEMBER 1987 UNTIL & PLANNED SHUTDOWN IN APRIL 1988 TO CLEAN CONDENSER TUEES.
- * FUEL CLADDING LEAK DEVELOPED AT END OF MARCH 1988. OPERATING AT REDUCED POWER TO MINIMIZE ACTIVITY RELEASES

LIMERICK UNIT 1

PLANT/LICENSES PERFORMANCE (CONTINUED)

PERFORMANCE INDICATOR OVERVIEW

TPENDS: PLANT DATA LAST 2 CUARTERS PELATIVE TO THE PREVIOUS 4 QUARTERS DEVIATIONS: PLANT DATA RELATIVE TO INDUSTRY DATA LAST 4 QUAPTERS (DATA THROUGH THE SECOND QUARTER OF 1988 INCLUDED)

INCICATOR	TREND	DEVIATION
AUTO SCRAMS TOTAL		В
SAFETY SYSTEM ACTUATIONS	1	В
SIGNIFICANT EVENT FREQUENCY		A
SAFETY SYSTEM FAILURES		Е
FCFCED OUTAGE PATE	D	1
EQUIPMENT FORCED CUTAGES	1.1	A

I = IMPROVED A = ABOVE AVERAGE D = DECLINED B = BELCW AVERAGE -- = NO CHANGE

LIMERICK, UNITS 1 AND 2 PLANT/LICENSEE PERFORMANCE (CONTINUED)

SPECIAL LICENSING ACTIONS (JUNE 1987 TO PRESENT)

- NO EMERGENCY OR EXIGENT TS CHANGES
- * ONE TEMPORARY WAIVER OF COMPLIANCE ON ORGANIZATIONAL CHANGES

SIGNIFICANY __ FORMANCE IMPROVEMENT PROGRAMS UNDERWAY OR PLANNED

- MAJOR CORPORATE AND SITE REORGANIZATIONS
- CONDUCTING IDCA FOR UNIT 2 IN RESPONSE TO SALP
- REORGANIZATION OF NEE FROM A COMPLIANCE FOCUSED REVIEW TO AN EXAMINATION OF PROCESS AND PLANT PERFORMANCE
- CONSOLIDATION OF ALL PREVIOUSLY FRAGMENTED OF AND OC FUNCTIONS INTO A SINGLE QUALITY UNGANIZATION
- * STRENGTHENED AND INCREASED SCOPE OF ISEP PROGRAMS
- INCREASED ATTENTION TO WATER CHEMISTRY

LIMERICK 1

NRC SALP RATINGS

FUNCTIONAL AREA	PERIOD 12/1/84-1/	31/86	PERIOD 2/1/86-1/31/87	PERIOD 2/1/87-4/30/88
PLANT OPERAT	IONS	1	1	1
RADIOLOGICAL		2	1	
MAINTENANCE		2	1	1
SURVEILLANCE		2	1	1
ENGINEERING TECHNICAL S	AND UPPORT NOT	EVALUAT	ED 1	2
EMERGENCY PR	EPAREDNESS	1	1	2
SECUPITY AND SAFEGUARDS		3	2	1
SAFETY ASSES GUALITY VER	SMENT IFICATION		٠	1
TRAINING AND QUALIFICATI EFFECTIVENE	CN	24	1	**
LICENSING AC	TIVITIES	1	2	***
ASSURANCE OF	QUALITY	1	1	***

*NOT EVALUATED AS A SEPARATE FUNCTIONAL AREA LAST PERIOD **CRITERION FOR ALL FUNCTIONAL AREAS, AND NO LONGER A SEPARATE AREA ***NOW EVALUATED UNDER SAFETY ASSESSMENT

LIMERICK 2

NRC SALP PATINGS

FUNCTIONAL AREA

PERIOD 1/1/86-7/31/87

CONTAINMENT, SAFETY-RELATED STRUCTURES, AND MAJOR STEEL SUPPOR SOILS & FOUNDATIONS	RTS,
ENGINEERING	2
PIPING SYSTEMS AND SUPFORTS	1
SAFETY-RELATED COMPONENTS-MECHANIC	AL 1
AUXILIARY SYSTEMS	1
ELECTRICAL EQUIPMENT AND CABLES	1
INSTRUMENTATION AND CONTROL SYSTEM	S 1
LICENSING ACTIVITIES	1
PREOPERATIONAL TESTING	NOT RATED
ASSURANCE OF CUALITY	2

NOTE: THIS IS THE FIRST SALP PEPORT THAT SPECIFICALLY ADDRESSES LIMERICK GENERATING STATION, UNIT 2, ACTIVITIES. CONSTRUCTION OF UNIT 2 WAS SUSPENDED IN DECEMBER 1983, AT WHICH TIME UNIT 1 WAS STILL UNDER CONSTRUCTION. ALL CONSTRUCTION ACTIVITIES WERE PREVIOUSLY EVALUATED IN A SINGLE FUNCTIONAL AREA WITH UNIT 1 AND THE OVERALL PATING WAS CATEGORY 1. THE LAST CONSTRUCTION SALP COVERED THE ASSESSMENT PERIOD OF 12/1/83 TO 11/30/84 AND WAS ISSUED ON FEBRUARY 7, 1985. PREVIOUS PERFORMANCE IS NOT DIRECTLY RELEVANT TO CURRENT PERFORMANCE DUE TO DIFFERENCES IN CONSTRUCTION PRACTICES.

8 1

LIMERICK, UNITS 1 AND 2 LICENSING ACTIONS - STATUS BACKLOG OVERVIEW

LAST BRIEFING (6/18/87)		CURPENT ADDI (9/30/88)		ADDE	ED COMPL		PLETED
UNIT 1 UNIT 2 TOTAL	20 25	16 7 23		11 7 18			15 20
					CAT 1	CAT 2	CAT 3
AMENDMENT	REQUESTS	RECEIVED A	FTEP 9/4/8	7	0	Lj	C
AMENDMENT COMPLETED	PEQUESTS BY PM	RECEIVED A	FTER 5/4/8	7	С	2	0
AMENDMENT	REQUESTS BY PM (6)	PECEIVED P	RIOR TO 9/4 ESENT)	4/87		1	

"PREDECISIONAL DOCUMENT"

8

÷

LIMERICK, UNITS 1 AND 2 INSPECTION FINDINGS

INSPECTIONS CONDUCTED (JUNE 1987 TO PRESENT)

UNIT 1

- 32 ROUTINE INSPECTIONS
- 3 SPECIAL TEAM INSPECTIONS OPERATIONAL FEADINESS PRIOR TO STARTUP FROM REFUELING EC PROCEAM

ANNUAL FULL-PARTICIPATION EMERGENCY PREPAREDNESS EXERCISE

UNIT 2

- * 26 ROUTINE INSPECTIONS
- * 1 CONSTRUCTION TEAM INSPECTION
- 2 IDCA TEAM INSPECTIONS

VIOLATIONS

- ONE ENFORCEMENT CONFERENCE ON REPORTABILITY OF DESIGN PROBLEM IN BOTH UNITS 1 AND 2
- * UNIT 1 1 LEVEL III, 8 LEVEL IV, 2 LEVEL V
- * UNIT 2 4 LEVEL IV, 3 LEVEL V

ALLEGATIONS

NONE OPEN

"PREDECISIONAL DOCUMENT"

ð

LIMERICK, UNITS J AND 2 LICENSING ACTIONS - STATUS (CONTINUED)

MAJOR CURRENT ISSUES IN PROGRESS

UNIT 1

. .

- !ST
- SALEM ATWS (2.1, 2.2, 4.5.2 AND 4.5.3)

UNIT 3

- PSI
- TSs
- * IDVP

MAJOR PLANT SPECIFIC ISSUES COMPLETED (JUNE 1987 - PRESENT)

UNIT 1

- ISI
- * 10 CFR 50,62 REVIEWS (ATWS RULE)
- TURBINE INSPECTION PROGRAM
- * ASLB HEARING ON TS AMENDMENT

MAJOR GENERIC ISSUES

- IST RESPONSE TO REI EXPECTED NOVEMBER 1988
- SALEM ATWS SERS EXPECTED DECEMBER 1988
 "PREDECISIONAL DOCUMENT"

LIMERICK, UNITS 1 AND 2 PLANT/LICENSEE PERFORMANCE

PLANT PEPSONNEL OVERVIEW

- STABLE WORK FORCE-LOW TURNOVER RATE
- 6 CPERATING SHIFTS (8% HOURS DURATION FOR OVERLAP)
 - 1 SHIFT IN TRAINING AT ANY GIVEN TIME
 - 1 SHIFT USED AS "UTILITY AND RELIEF" AT ANY GIVEN TIME
 - POTATE WITH CLOCK (I.E., DAY, AFTERNOON, NIGHT, TRAINING AND UTILITY), OPERATORS WORK DAY SHIFT OVER HALF THE TIME)
- * 6 STAS, ALL WITH ENGINEERING DEGREES PLUS 1 BACKUP. ROTATE WITH THEIR SHIFT
- * 42 LICENSED OPERATORS ON SHIFT (20 SRO, 22 RO), 20 ADDITIONAL SROS IN MANAGEMENT AND ENGINEERING
- ALL TRAINING PROGRAMS ARE ACCREDITED BY INPO
- * FITNESS FOR DUTY AND MANDATORY DRUG TESTING PROGRAMS INPLACE

LIMERICK, UNITS 1 AND 2 PLANT/LICENSEE PERFORMANCE (CONTINUED)

MAJOR OPERATING EVENTS

- * FUEL CLADDING LEAKS OCCUPING SINCE MARCH 1988
- RUPTURE OF EHC PIPING FOLLOWING MODIFICATION CAUSED TURBINE TRIP AND SCRAM.
- OPERATING VALVES OUT OF SEQUENCE WHEN SWITCHING RHR FUMPS DRAINED 60" OF WATER FROM REACTOR VESSEL INTO SUPPRESSION POOL

SUSQUEHANNA, UNITS 1 AND 2 PLANT/LICENSEE PERFORMANCE

OVERVIEW

. .

- TWO UNITS SITE CE BWR 4
- MARK 11 CONTAINMENT
- * PROJECT MANAGER TRAVEL SINCE LAST BRIEFING
 - 6 VISITS TO THE SITE/LICENSEE HQ
 - _ 8 VISITS TO THE REGION
- * NEW FIFTH EMERGENCY DIESEL GENERATOR (PM WALKDOWN PRIOR TO APPROVAL)
- * PERFORMED SPECIAL INSPECTIONS
 - ECR FOR VENTING
 - ELECTRICAL ISOLATION ALLEGATION
- * EMERGENCY OPERATIONS FACILITY TECHNICAL SUPPORT CENTER AND OPERATIONS SUPPORT CENTER ARE WELL EQUIPPED
 - SUSQUEHANNA SIMULATOR OPERATIONAL (SINGLE UNIT ONLY)
 - INDEPENDENT VERIFICATION OF EMERGENCY RESPONSE OF THE PLANT SYSTEMS AND OFFSITE EMERGENCY RESPONSE CAPABILITY COMPLETED
- * LICENSEE PARTICIPATED IN IDCOR IPE PROGRAM DEVELOPMENT: ON 12-11-87 GAVE NPC MANAGEMENT EXCELLENT PRESENTATION ON INSIGHTS GAINED FROM IPE ANALYSES.

• . . .

SUSQUEHANNA, UNITS 1 AND 2 PLANT /LICENSEE PERFORMANCE (CONTINUED)

- EFFICIENT EMERGENCY PREPAPEDNESS PROGRAM AND WELL TRAINED EMERGENCY RESPONSE PERSONNEL
- * HARRY KEISER PROMOTED TO SENIOR VICE PRESIDENT-NUCLEAR (VICE FRESIDENT-NUCLEAR OFERATIONS POSITION NOT FILLED): MONITOR FOR ANY CHANGES IN PERFORMANCE
- LICENSEE IS ENGAGED IN COST REDUCTION EFFORTS: MONITOR IMPACTS ON SAFETY

SUSQUEHANNA, UNITS 1 AND 2 PERFORMANCE TRENDS

SALP (PEPIOD ENDED JANUARY 31, 1988)

NINE RATINCS OF "1"

. .

- NO PATINGS OF "3"
- IMPROVED IN QUALITY ASSURANCE
- DECLINED IN PADIOLOGICAL CONTROLS AND ENGINEERING:
 THE LICENSEE PRACTICE OF FREQUENT SUPERVISOR ROTATION LED TO SUPERVISOR NOT MEETING THE PECUIRED TECHNICAL QUALIFICATIONS OF RADIOLOGICAL CONTROLS SUPERVISOR
- * LICENSEE'S ENGINEERING RESOURCES APPEARED STRAINED

PERFORMANCE INDICATORS

- BETTER THAN AVERAGE: ONE OF THE BEST PEPFORMERS IN THE REGION
- BOTH UNITS IMPROVED IN 4 AREAS EACH
- BOTH UNITS DECLINED IN 1 AREA EACH
- UNIT 1 WAS ABOVE AVERAGE IN 4 AREAS AND UNIT 2 WAS ABOVE AVERAGE IN 5 AREAS
- UNIT 1 WAS BELOW AVEPAGE IN 2 AREAS AND UNIT 2 WAS FELOW AVERAGE IN 1 AREA

SUSQUEHANNA, UNITS 1 AND 2 PERFORMANCE TRENDS (CONTINUED)

GENERAL

. .

- MANAGEMENT CONTINUES TO BE CLOSELY INVOLVED IN PLANT OPERATIONS
- * PECENT REFUELING OUTAGE MANAGEMENT FOR UNIT NO. 2 HAS RUN INTO NULTIPLE PROBLEMS - REGION I AND NRR ARE MONITORING POOT CAUSE EVALUATIONS

SUSQUEHANNA, UNITS 1 AND 2 LICENSING ACTIONS STATUS

LICENSEE HAS BEEN VERY ACTIVE: THE PM HAS HANDLED A HEAVY LOAD IN A TIMELY FASHION

NTICIPATED LICENSING ACTIONS NEXT 12 MONTHS

BY THE END OF 1ST QUARTER OF 1989 THE LICENSEE EXPECTS TO SUEMIT 36 NEW PLANT SPECIFIC ACTION PEQUESTS: LARGELY CATEGORY 2 WORKS, MOSTLY HANDLED BY THE PM

FIRE PROTECTION REVIEW REPORT REVISION SUBMITTED JUNE 30, 1988

COMMON MODE FAILURE POTENTIAL ALLEGATION/ELECTRICAL AND CONTROL ISOLATION ISSUES UNDER REVIEW

ATWS RULE REVIEW: SYSTEMS REVIEW COMPLETE/INST, 2 CONT. REVIEW PENDING

EQUACY OF PLANS/SCHEDULES

LICENSEE STAFF WELL PREPARED FOR MEETINGS

EMERGENCY PREPAPEDNESS RATED SALP CATEGORY 1

SECURITY AND SAFEGUARDS CAPABILITY RATED SALP CATEGORY 1

GUALITY ASSURANCE RATED SALP CATEGORY 1

SUSCUEHANNA UNITS 1 AND 2 LICENSING ACTIONS STATUS - (CONTINUED)

RADIOLOGICAL CONTROLS RATED SALP CATEGORY 2

. . .

¢

 OUTAGE MANAGEMENT DECLINED IN CURRENT UNIT 2 OUTAGE-RECENT SALP RATING IS CATEGORY 1

SUSQUEHANNA UNITS 1 AND 2 LICENSEE INITIATIVES

REGULAR GUARTERLY MEETINGS WITH NRC TO DISCUSS LICENSING ISSUES AND SCHEDULES

ADVANCE PLANNING INCLUDES CLOSE INTERFACE WITH NRC PRICE TO SUBMITTAL

INITIATES SAFETY STUDIES 4'D INFORMS NPC OF POTENTIAL NEW ISSUES

PARTICIPANT IN IDCOR IPE METHODOLOGY DEVELOPMENT

AINTAINS ACTIVE RISP ASSESSMENT CAPABILITY AND REVIEWS ALL ICENSING AND UTILITY INITIATED ACTIONS IN TERMS OF RISK EDUCTION

AVE EXCELLENT BRIEFING TO THE NRC MANAGEMENT ON INSIGHTS AINED FROM IPE ANALYSES

SUSQUEHANNA, UNITS 1 AND 2 SUMMARY OVERVIEW

STRENGTHS

- DEDICATED TOP MANAGEMENT PROMOTES HIGH STANDARDS AND EXCELLENCE IN PERFORMANCE: GOOD SAFETY ETHIC
- A SUBSTANTIAL EFFORT IS BEING PUT INTO STREAMLINING TECHNICAL SPECIFICATIONS
 - INSTALLATION OF THE FIFTH EMERGENCY DIESEL GENERATOR HAS ENHANCED FELIABILITY OF POWER SUPPLY
- CONTINUOUS SELF ASSESSMENT AND INDEPENDENT VERIFICATION OF OTHERS' WORK (E.G. CONTRACTORS ANALYSES): THE NRC SALP ASSESSMENTS VIEWED SERIOUSLY
- * THE LICENSEE FIRMLY BELIEVES IN INHOUSE ENGINEERING AND RISK ANALYSIS CAPABILITY WITH MINIMAL CONTRACTOR SUPPORT
- PROCEDURES IMPROVEMENT AND PLANT MODIFICATIONS
- * INDEPENDENT VERIFICATION OF EMERGENCY PESPONSE OF THE PLANT SYSTEMS AND OFFSITE SYSTEMS
- * 10 CFR 50.59 REVIEWS ARE WELL DOCUMENTED AND GIVE ASSURANCE OF WELL MANAGED MODIFICATION PROGRAM

SUSQUEHANNA, UNITS 1 AND 2 SUMMARY O'ERVIEW (CONTINUED)

WEAKNESSES

- CURPENT SALP INDICATES PROBLEMS IN THE RADIOLOGICAL CONTROLS PROCEAN AND ENGINEERING RESOURCES MAY BE STRESSED
- EQUIPMENT QUALIFICATION PROGRAM APPEARS TO HAVE SOME PROBLEMS: REGION 1 ESCALATED ENFORCEMENT CONFERENCE WITH THE LICENSEE, MINIMUM CIVIL PENALTY IMPOSED.
- RECENT UNIT 2 CUTAGE MANAGEMENT PROBLEMS MAY BE INDICATIVE OF DECLINING MIDDLE MANAGEMENT CONTROL ON THE OUTAGES: LICENSEE HAS SET UP A TASK FORCE UNDER CHUCK MYERS TO ASSESS THE PROBLEMS AND PROPOSE FIXES

OVERALL ASSESSMENT

- CONTINUED HIGH LEVEL MANAGEMENT ATTENTION IS EVIDENT
- PRESENCE OF MCTIVATED WORK CULTURE
- EFFORTS UNDERWAY TO IMPROVE FIRE PROTECTION AND EG
 PROGRAMS. REVISED FIRE PROTECTION PROGRAM EXCEEDS NRC REQUIREMENTS
- UNIT 2 OUTAGE DIFFICULTIES NEED A CLOSER LOOK: NRR/PEGICM I WILL MONITOR AND REVIEW TASK FORCE REPORTS
- NEC EXPENDED CONSIDERABLE INSPECTION RESOURCES DURING LAST SALF PEPICD (ABOUT 5000 INSPECTION HOURS IN 18 MONTHS)

SUSQUEHANNA, UNITS 1 AND 2 PLANT/LICENSEE PERFORMANCE

PLANT PERSONNEL OVERVIEW

- APPROXIMATELY 1200 LICENSEE PERSONNEL ON SITE
- STABLE WOPKFORCE
- 6 ROTATIONAL WORK SHIFTS (3 WORKING 1 OFF 1 TRAINING 1 RELIEF)
- * 35 SENIOR PEACTOR OPERATORS AND 29 REACTOR OPERATORS
- 23 SENIOR REACTOP OPERATORS AND 24 REACTOR OPERATORS ASSIGNED TO SHIFT DUTIES
- 6 SHIFT TECHNICAL ADVISERS ASSIGNED TO WORK SHIFTS
- INPO ACCREDITED TRAINING
- GOOD PAST RECORD OF PASSING REACTOR OPERATUR EXAMINATIONS
- * BUT IN 1987 4 FAILED AND 5 PASSED

MAJOR OPERATING EVENTS

- UNIT 2 HAD A CONTINUOUS RUN OF 313 DAYS RECORD RUN FOR GE SECOND CYCLE OFERATION
- * UNIT 2 FEEDWATER SPARGER NOZZLES DAMAGED DURING STEAM SEPARATOR INSTALLATION (FOLLOWING A REFUELING OUTAGE)

SUSQUEHANNA, UNITS 1 AND 2 PLANT/LICENSEE PEPFORMANCE (CONTINUED)

MAJOR OPERATING EVENTS

- FUEL POOL WATER DEMIN RESIN INADVERTENTLY FLUSHED INTO THE PLANT PIPING LEADING TO RADIATION HOT SPOTS IN THE PIPING
 - PROBLEM EVENTS APPEAR TO COCUR DURING OUTAGES

SUSQUEHANNA, UNITS 1 AND 2 PLANT/LICENSEE PERFORMANCE (CONTINUED)

PERFORMANCE INDICATOP OVERVIEW

TRENDS: PLANT DATA LAST 2 GUARTERS PELATIVE TO THE PREVIOUS 4 CUARTERS

DEVIATIONS: PLANT DATA RELATIVE TO INDUSTRY DATA LAST 4 CUAPTERS (DATA THPOUGH THE SECOND QUARTER OF 1988 INCLUDED)

INDICATÓR	UNIT 1 UNIT 2		DEVIATION UNIT 1 UNIT 2	
AUTO SCRAMS TOTAL	D	I	A	A
SAFETY SYSTEM ACTUATIONS		1	A	A
SIGNIFICANT EVENT FREQUENCY	I	D	Б	В
SAFETY SYSTEM FAILURES	I		A	A
FORCED OUTAGE RATE	I	1	P	А
EGUIPMENT FORCED OUTAGES	1	1	Α	A

I = IMPROVED D = DECLINED -- = NO CHANGE

A = ABOVE AVERAGE B = BELOW AVERAGE

SUSGUEHANNA, UNIT 1 AND 2 PLANT/LICENSEE PERFORMANCE (CONTINUED)

SPECIAL LICENSING ACTIONS (JUNE 1987 TO PRESENT)

* 3 EMERGENCY TECH SPEC CHANGES

.

NO DISCRETIONARY ENFORCEMENTS/TEMPORARY WAIVER OF COMPLIANCE

SIGNIFICANT PERFORMANCE IMPROVEMENT PROGRAMS UNDERWAY OR PLANNED * NONE

SUSQUEHANNA, UNITS 1 AND 2 INSPECTION FINDINGS

INSPECTIONS CONDUCTED (APRIL 1987 TO PRESENT)

- * ROUTINE INSPECTIONS: 23 CN UNIT 1 18 ON UNIT 2
- VENTING EOP INSPECTION BY NRR MARCH, 1988

VICLATIONS

. .

- * NO ESCALATED ENFORCEMENT
- UNIT 1 4 LEVEL IV
 - UNIT 2 1 LEVEL IV AND 1 LEVEL V

ALLEGATIONS

9 OPEN ALLEGATIONS

LICENSING ACTIONS - STATUS BACKLOG OVERVIEW

AST BRIEFING (6/11/87)		CURRENT (E/C1/88)	ADDED	COMPLETED
UNIT 1	21	19	20	22
INIT 2	17	17	25	25
TCTAL	38	36	45	47

SUSQUEHANNA, UNIT 1 AND 2

LICENSING ACTIONS - STATUS (CONTINUED)

MAJOR CUPPENT ISSUES IN PROGRESS

.

- * FEEDWATER SPARGER DAMAGE RECOVERY AND RESTART JUSTIFICATION
- * DCPDR REVIEW ESSENTIALLY COMPLETE
- * INSERVICE TESTING PROGRAM UNDER REVIEW
- * ELECTRICAL & CONTROL ISOLATION ALLEGATION UNDER REVIEW

MAJOR PLANT SPECIFIC ISSUES COMPLETED (JUNE 1987 - PRESENT)

- * REVIEW OF CORE PHYSICS REPORT
- PHR WATERHAMMER MODIFICATION PEVIEW
- JUSTIFICATION FOR CONTINUED OPERATION WITH DAMAGED FEEDWATER SPARGER NOZZLES
- * SINGLE LOOP OPERATION AND THERMAL HYDRAULIC STABILITY

SUSQUEHANNA, UNITS 1 AND 2 LICENSING ACTIONS - STATUS (CONTINUED)

MAJOR GENERIC ISSUES

0

0

NUREG-0737 ITEMS COMPLETE

 NUREG-0737 SUPPLEMENT 1 ITEMS IMPLEME (1ED. REVIEWES COMPLETE EXCEPT FOR: PROCEDURES GENERATION PACKAGE SPDS REVIEW DCFDF REVIEW METEOROLOGICAL DATA UPGRADE

FIRE PROTECTION REPORT SCHEDULED TO BE COMPLETE IN JUNE 1988

OTHER MPAS COMPLETE EXCEPT FOR: A-20 OPERATING REACTOR REVIEWS (10 CFR 50.62) FOUR PAPTS OF SALEM ATWS GENERIC LETTER

1

ø

12.

SUSQUEHANNA, UNITS 1 AND 2 SALP CATEGORY TENDS

FUNCTIONAL AREA	PERIOD 2/1/84-4/30/85	PERIOD 5/1/85-7/31/86	FEFICD 8/1/86-1/31/88
PLANT OPERATIO	NS 2	1	1
CHEMISTRY AND RADIOLOGICAL CONTPOLS	1	1	2
MAINTENANCE	1	1	1
SURVEILLANCE	2	1	1
EMERGENCY PREPAREDNESS	1	1	1
SECURITY AND SAFEGUARDS	1	1	1
REFUELING AND (MANAGEMENT	DUTAGE 1	1	1
ASSURANCE AND QUALITY	NOT EVALUAT	ED 2	1
LICENSING ACTIV	/ITIES 1	1	1
ENGINEERING SUPPORT	NOT EVALUAT	ED 1	2
TRAINING AND CUALIFICATION EFFECTIVENESS	NOT EVALUAT	ED 1	1

"PREDECISIONAL DOCUMENT"

-

.

SHOREHAM PLANT/LICENSEE_PERFORMANCE

OVERVIEW

- * LICENSEL: LONG ISLAND LIGHTING COMPANY
- * LOCATION: SHOREHAM, NO. SHORE OF LONG ISLAND, MY
- POPULATION: 10 MILES 164,442 (1990 PROJECTION)
 50 MILES 5,750,606 (1990 PROJECTION)
- * ARCHITECT-ENGINEER: STONE & WEBSTER
- REACTOR TYPE: BWR-4
- CONTAINMENT TYPE: MARK 11
- * POWER: 846 MWE
- COOLING: ONCE-THROUGH, LONG ISLAND SOUND
- OPERATING LICENSE: NPF-36, JULY 3, 1985 (57)
- TRAINING CENTER AND SIMULATOR: OPERATIONAL
- OTHER: HEAVILY LITIGATED (EMERGENCY PLANNING ISSUES)

SHOREHAM

PERFORMANCE TRENDS

SALP (MOST RECENT ENDED 7/31/87)

- 6 CATEGORY 1s: PLANT OPERATIONS & STARTUP TESTING,
 RADIOLOGICAL CONTROLS, EMERGENCY PPEPAREDNESS, SECURITY AND SAFEGUARDS, LICENSING ACTIVITIES, AND ASSURANCE OF QUALITY
- A CATEGORY 2s: MAINTENANCE (IMPROVING), SURVEILLANCE, ENGINEERING AND CORPORATE TECHNICAL SUPPORT, AND TRAINING AND CUALIFICATION EFFECTIVENESS (IMPROVING)
- * NO CATEGORY 3s

PEPFORMANCE INDICATORS (DATA THROUGH 06/30/88)

- * ABOVE AVERACE DEVIATIONS FROM NEWFR PLANTS IN 6 APEAS
- * BELOW AVEPAGE DEVIATION FROM NEWER PLANTS IN O AREAS
- IMPPOVED TRENDS IN 1 INDICATOR
- * ZERO TREND IN 5 INDICATORS

GENERAL

OVERALL PERFORMANCE IS IMPROVING

SHOREHAM

LICENSING ACTIONS - STATUS

ANTICIPATED LICENSING ACTIONS NEXT 12 MONTHS

- DECOMMISSIONING (OR)
- FULL POWER LICENSE (OR)
- 257 OF FU'L POWER LICENSE
- COMPLETED PGP REVIEW
- EDG LICENSE CHAMGE
- ORGANIZATION CHARTS REMOVED FROM TECH SPEC
- ASLF FINDING ON REMANDED ISSUES (EBS, HOSPITAL EVACUATION, SCHOOL BUS ROLE CONFLICT)
 - ASLE FINDING ON LEGAL AUTHORITY ISSUES
 - ASLAB FINDING ON LILCO'S APPEAL OF THE 2/1/88 ID EXERCISE OF PLAN

SHOPEHAM

LICENSING ACTIONS - STATUS (CONTINUED)

ADECUACY OF PLANS/SCHEDULES

- INTEGRATED LIVING SCHEDULE (LITTLE INTEREST)
- SAP 11 (LITTLE INTEREST)

LICENSEE INITIATIVES

4

- SUPPLEMENTAL CONTAINMENT SYSTEM
- DAILY TELEPHONE CONTACT WITH PROJECT MANAGER

MAJOR CURPENT ISSUES IN PROGRESS

- FULL POWER LICENSING (PEMANDED & LEGAL AUTHORITY ISSUES, AND LITIGATION OF SECOND EXERCISE)
- 25% POWER LICENSING (SER EXCLUDING EP IN FINAL CONCURRENCE).
- DECOMMISSIONING (INFORMATION PAPER IN FINAL CONCURRENCE)

MAJOR PLANT SPECIFIC ISSUES COMPLETED (JUNE 1987 - PRESENT)

- * 50.54(A) EXEMPTION
- * SECOND GRADED EXERCISE OF THE EMERGENCY PLAN
- INSTALLATION OF THE REDUNDANT SET OF EDGS (PLANT NOW HAS 6 EDGS)
- GUIDANCE ON SUPPLEMENTAL CONTAINMENT SYSTEM

.

SHOREHAM

LICENSING ACTIONS - STATUS (CONTINUED)

MAJOR GENERIC ISSUES

- NUREG-0737 SUFFLEMENT 1 ITEMS COMPLETE EXCEPT FOR:
 - PROCEDURES GENERATION PACKAGE
 - REGULATORY GUIDE 1.97 (IMPLEMENTATION)
 - SPDS
 - DCRDR

OTHER MAJOR MPAS COMPLETE EXCEPT FOR:

- SALEN ATWS ISSUES
- INSERVICE TESTING (IST)
- INSERVICE INSPECTION (ISI)

SHOREHAM.

SUMMARY OVERVIEW

STRENGTHS

DEDICATED AND COMPETENT PLANT STAFF

GOOD PROGRAMS IN CA, FADIOLOGICAL PROTECTION, SECURITY AND EMEPGENCY PLANNING

CA INVOLVED IN PLANT OPERATIONS AND MAINTENANCE

RESPONSIVE MANAGEMENT

VEAKNESSES

2

- * LACK OF OPERATIONAL EXPERIENCE (DUE TO DELAY) IN LICENSING
- COMERING STAFF MORALE DUE TO NY/LILCO AGREEMENT (BEING MONITORED BY SRI W/SR LILCO MANAGEMENT, NO SAFETY PROBLEM IDENTIFIED YET)
- LAST SALP NOTED LACK OF FOLLOW UP OF MAINTENANCE PROJECTS BY FIRST LINE MANAGEMENT (LILCO RECENTLY FORMED A PLANNING MAINTENANCE GROUP - TO EARLY TO ASSESS THE EFFECT OF CHANGE, BUT APPEARS TO BE IN COPRECT DIRECTION).
 - ALARA CONCERNS IN RADWASTE AREA (LILCO IDENTIFIED, SRI & REG I ARE FOLLOWING CORRECTIVE ACTIONS)

SHOREHAM

SUMMARY OVERVIEW (CONTINUED)

SUMMARY ASSESSMENT

SITE MANAGEMENT TAKES AN ACTIVE POLE IN DAY-TO-DAY OPERATIONS
 COPFORATE MANAGEMENT PROVIDES STRONG SUPPORT FOR PROGRAMS
 OVERALL PLANT PERFORMANCE IS SATISFACTORY

SHOREHAM

PLANT/LICENSEE PERFORMANCE

PLANT PERSONNEL OVERVIEW

٠

0

- STABLE WORK FORCE (VERY LOW TURNOVER 4 OR 5 LICENSES HAVE LEFT SINCE LICENSING STARTED
 - 6 OPERATING SHIFTS (8-HOUR DURATION)
- * 1 SHIFT IN TRAINING AT ANY GIVEN TIME.
- 21 LICENSED OPERATORS ON PLANT STAFF 21 SROs
- 37 LICENSED OPERATORS ON SHIFT DUTIES 13 SROs, 24 ROS
- * 6 SHIFT ENGINEERS (STAS) ALL DEGREED
- * TRAINING PROGRAMS ACCREDITED BY INPO
 - SHOREHAM BECAME A DRANCH MEMBER OF THE MATIONAL ACADEMY FOP NUCLEAR TRAINING ON APPIL 19, 1988 WHEN THE FOLLOWING PROGRAMS WERE ACCREDITED (EQUIPMENT, REACTOR, & SENIOR REACTOR OPERATORS, HEALTH PHYSICS, & RADIOCHEMISTRY TECHNICIANS AND SHIFT TECHNICAL ADVISOR)
 - NEXT INPO ACCREDITATION TEAM VISIT WILL BE CONDUCTED THE WEEK OF MAY 9, 1988 FOR THE PEMAINING PROGRAMS OF: (ELECTRICAL MAINTENANCE, MECHANICAL MAINTENANCE, 1&C TECHNICIANS AND TECHNICAL STAFF AND MANAGERS

SHOREMAM

PLANT/LICENSEE + SPECEMANCE (CONTINUED)

MAJOR OPERATING EVENTS

* NONE

SHOREHAM

PLANT/LICENSEE PERFORMANCE (CONTINUED)

TRENDS: PLANT DATA LAST 2 CUAPTERS RELATIVE TO THE PREVIOUS 4 QUARTERS DEVIATIONS: PLANT DATA RELATIVE TO INDUSTRY DATA LAST 4 QUARTERS (DATA THROUGH THE SECOND QUAPTER OF 1988 INCLUDED)

INDICATOR	TREND	DEVIATION
AUTO SCRAMS TOTAL		A
SAFELY SYSTEM ACTUATIONS		A
SIGNIFICANT EVENT FREQUENCY		1
SAFETY SYSTEM FAILUPES	1	A
FOPCED OUTAGE RATE		A
EQUIPMENT FORCED CUTAGES		А

1		IMPROVED
Ď	=	DECLINED
	*	NO CHANGE

A = ABOVE AVERAGE B = BELCW AVERAGE

SHOREHAM

PLANT/LICENSEE PERFORMANCE (CONTINUED)

SPECIAL LICENSING ACTIONS (1/1/87 TO PRESENT)

NO EMERGENCY TECH SPEC CHANGES

Å

NO DISCRETIONARY ENFORCEMENTS/TEMPORARY WAIVERS OF COMPLIANCE

SIGNIFICANT PEPFORMANCE IMPROVEMENT PROGRAMS UNDERWAY OR PLANNED

- * REVISING EOPs TO REVISION 4
- * DEVELOPING ACTION PLAN TO IMPROVE SALP RATINGS
- RADWASTE AREA ALARA IMPROVEMENT PROGRAM
- * FORMATION OF MAINTENANCE PLANNING GROUP

SHOREHAM

INSPECTION FINDINGS

INSPECTIONS CONDUCTED (JUNE 1987 TO PRESENT)

- 15 POUTINE INSPECTIONS
- * 2 SPECIAL INSPECTIONS

VIOLATIONS

- NO ESCALATED ENFORCEMENT
- * 2 LEVEL IV
 - 2 LEVEL V

ALLEGATIONS

* 1 OPEN ALLESATION

LICENSING ACTIONS - STATUS BACKLOG OVERVIEW

LAST BRIEFING	(4/10/87)	CU (4	RRENT /C1/88)	ADDED	CO	MPLETED
29			33		13		7 .
					CAT 1	CAT 2	CAT 3
AMENDMENT	PECUESTS	RECEIVED	AFTER	9/4/87	0	4	0
AMENDMENT	RECUESTS BY PM	PECEIVED	AFTER	9/4/87	0	C	C
AMENDMENT (674/87 T)	REQUESTS	RECEIVED	PRIOR	TO 9/4	/87 COMPL	ETED BY I	PM <u>1</u>

SHOPEHAM

NUCLEAR POWER STATION

SALP SUMMARY					
PERIOD ENDING	02/85	02/86	07/87		
PLANT OPERATIONS	1	2	1		
RADICLOGICAL CONTROLS AND CHEMISTRY	1	3	1		
MAINTENANCE AND CTHEP OUTAGE MANAGEMENT	1	2	2		
SURVEILLANCE	1	2	2		
EMERGENCY PREP.	*	1	1		
SECURITY & SAFEG.	1	1	1		
ENGINEERING SUPPORT	1	-	2		
LICENSING ACTIVITES	2	3	1		
ASSURANCE OF QUALITY	-	2	1		
TRAINING & CUALIFICATION EFFECTIVENESS		3	2		