

OCT 4 1988

Docket No. 50-346

Toledo Edison Company
ATTN: Mr. Donald Shelton
Vice President
Nuclear
Edison Plaza
300 Madison Avenue
Toledo, OH 43652

Gentlemen:

This refers to the special safety inspection conducted by Mr. D. S. Butler of this office on August 29 through September 2 and September 12-16, 1988, of activities at Davis-Besse Nuclear Power Station, Unit 1, authorized by NRC Operating license No. NPF-3, and to the discussion of our findings with you and others of your staff at the conclusion of the inspection. The purpose of the inspection was to review the Steam and Feedwater Rupture Control System modification.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original Signed by J. J. Harrison

J. J. Harrison, Chief
Engineering Branch

Enclosure: Inspection Report
No. 50-346/88031(DPS)

See Attached Distribution

8810120338 881004
PDR ADOCK 05000346
Q PDC

RIII *see*
Deb
Butler/lms/jk
1u/03/88

RIII
Don
Die
10/3/88

RIII
ro
DeFayette
10/3/88

RIII
JJA/rv
Gardner
10/4/88

RIII
JJH
Harrison
10/4/88

IEO1

OCT 4 1988

Distribution

cc w/enclosure:

L. Storz, Plant Manager

DCD/DCB (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII

Harold W. Kohn, Ohio EPA

James W. Harris, State of Ohio

Robert M. Quillin, Ohio

Department of Health

State of Ohio, Public

Utilities Commission