

OCT 03 1988

Docket No. 50-454

Docket No. 50-455

Commonwealth Edison Company
ATTN: Mr. Cordell Reed
Vice President
Post Office Box 767
Chicago, IL 60696

Gentlemen:

This refers to the routine safety inspection conducted by Ms. M. Smith and others of this office on September 19-22, 1988, of activities at the Byron Nuclear Generating Station, Units 1 and 2, authorized by NRC Operating Licenses No. NPF-37 and No. NPF-66 and to the discussion of our findings with Mr. R. Pleniewicz and others at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

"Original signed by W.D. Shafer"

W. D. Shafer, Chief
Emergency Preparedness and
Radiological Protection Branch

Enclosure: Inspection Reports
No. 50-454/88018(DRSS);
No. 50-455/88016(DRSS)

See Attached Distribution

RIII

RIII

RIII

RIII

RIII

Smith/ln
YES

Ploski
YES

Snel
YES

Hinds
10-02-88

Shafer

JE35
/

881003
8810120348
PDR ADOCK 05000454
PDC

OCT 03 1988

Distribution

cc w/enclosure:

T. J. Maiman, Vice President,
PWR Operations

H. Bliss, Nuclear
Licensing Manager

R. Pleniewicz, Station Manager
DCO/DCB (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII Byron

Resident Inspector, RIII

Braidwood

D. W. Cassel, Jr., Esq.

Richard Hubbard

J. W. McCaffrey, Chief, Public
Utilities Division

Diane Chavez, DAARE/SAFE

L. Olshan, NRR LPM

H. S. Taylor, Quality Assurance
Division

W. Travers, EPB, NRR

W. Weaver, FEMA, RV

R. Landsman, RIII