NRC Form 591		U.S. NUCLEAR REGULATORY COMMISSION
(12-81) 10 CFR 2.201	SAFETY INSPECTION	tified By: h. mclanar
1. LICENSEE General Electric 1100 Western Aven Lynn, Massochuse	Company 2. REGIONAL OFFICE USNRC 631 Por	
3. DOCKET NUMBER(S) 4	20-00815-05	April 2, 1986
those actions at this time.  3. During this inspection certain of your activities,	and the conditions of your license. The inspection and observations by the inspector. The findings as were observed.  Sken to correct the violations identified during the	n consisted of selective examinations of procedures as a result of this inspection are as follows:  e last inspection. We have no further questions on uirements.
labeled to indicate the presence of radioactive C		of sealed sources were not performed at the proper ondition Number were not properly maintained.
E. Documents were not properly posted or other	erwise made available. 10 CFR 19.11.	
F. Reports or notifications of with 10 CFR	or License Condition Nu	mber were not made in accordance
B604210274 B6042100000000000000000000000000000000000	PDR	REGION I IE:07
I hereby state that within 30 days the actions described. This statement of correct/ve actions is made in accordate NRC.	d by me to the Inspector will be taken to correct ince with the requirements of 10 CFR 2.201. No	the violations identified in the items checked above. further response will be submitted unless required by