Reference . B) '86 APR 16 AIO 38 UNITED STATES DOC CENTERNUCLEAR REGULATORY COMMISSION 1450 MARIA LANE, SUITE 210 Action By Responsible WALNUT CREEK, CALIFORNIA 94596 Eng. April 11, 1986 (Date) 12 Docket Nos. 50-528, 50-529 and 50-530 Info Arizona Nuclear Power Project Post Office Box 52034 Phoenix, Arizona 85072-2034 Process Follow Attention: Mr. E. E. Van Brunt, Jr., Executive Vice President Gentlemen: Subject: Systematic Assessment of Licensee Performance Report Numbers 50-528/85-36, 50-529/85-38 and 50-530/85-28 The SALP Board report was sent to you on December 19, 1985. No reply to the SALP report or meeting was requested; however, you were invited to discuss any questions concerning the report. To date, we have not yet received any written comments from you.

We identified two editorial errors in the SALP Board report after it was issued and they are corrected by the attached errata sheet.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the SALP Report will be placed in the NRC's Public Document Room, as will any comments you may wish to submit to NRC regarding the content of the SALP Report.

No reply to this letter i concerning the SALP repor

ined; however, should you have any questions would be pleased to discuss them with you.

Sincerely,

D. F. Kirsch, Director

Division of Reactor Safety and Projects

Enclosure:

Errata sheet w/original and corrected pages

cc w/enclosure:

J. Bynum, ANPP

T. D. Shriver, ANPP

W. E. Ide, ANPP

C. N. Russo, ANPP

Ms. Jill Morrison, PVIF

Lynne Barnabei (GAP)

Duke Railsback, Arizona Corp. Commission

Arthur C. Gehr, Esq., Snell & Wilmer

J. G. Partlow, IE

H. L. Thompson, NRR

E. Licitra, NRR

J. M. Taylor, IE

8605070100 860422 PDR ADOCK 05000528 G PDR