

Tennessee Valley Authority, Post Office Box 2000, Decatur, Alabama 35609-2000

Karl W. Singer  
Vice President, Browns Ferry Nuclear Plant

October 28, 1998

10 CFR 50.73

U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D. C. 20555

Gentlemen:


In the Matter of )  
Tennessee Valley Authority )

**BROWNS FERRY NUCLEAR PLANT (BFN) - UNITS 1, 2, AND 3 - DOCKET NOS. 50-259, 50-260, AND 50-296 - FACILITY OPERATING LICENSES DPR-33, 52, AND 68 - REVISED LICENSEE EVENT REPORT (LER) 50-259/1998-003-01**

LER 50-259/1998-003-00 was submitted on July 16, 1998, pursuant to 10 CFR 50.73(a)(2)(ii)(B), as an event or condition which resulted in the nuclear power plant being in a condition that was outside the design basis of the plant. This LER reported a condition which resulted in the required volume of nitrogen stored onsite for Containment Atmosphere Dilution not being sufficient to meet the design basis as stated in the Technical Specifications Bases.

The enclosed revised report provides additional details regarding corrective actions taken in response to this event.

Sincerely,

  
K. W. Singer

cc: See page 2

9811090180 981028  
PDR ADOCK 05000259  
S PDR

IE22/1

U.S. Nuclear Regulatory Commission  
Page 2  
October 28, 1998

Enclosure

cc (Enclosure):

Mr. A. W. De Agazio, Project Manager  
U.S. Nuclear Regulatory Commission  
One White Flint, North  
11555 Rockville Pike  
Rockville, Maryland 20852

Mr. Harold O. Christensen, Branch Chief  
U.S. Nuclear Regulatory Commission  
Region II  
61 Forsyth Street, S. W.  
Suite 23T85  
Atlanta, Georgia 30303

NRC Resident Inspector  
Browns Ferry Nuclear Plant  
10833 Shaw Road  
Athens, Alabama 35611

Mr. L. Raghavan, Senior Project Manager  
U.S. Nuclear Regulatory Commission  
One White Flint, North  
11555 Rockville Pike  
Rockville, Maryland 20852