Docket No. 50-454

Commonwealth Edison Company ATTN: Mr. Cordell Reed Senior Vice President Post Office Box 767 Chicago, IL 60690

Gentlemen:

This refers to the routine safety inspection conducted by Mr. K. D. Ward of this office on September 14, 20-22, 27-29, and October 17, 1988, of activities at Byron Station, Unit 1 authorized by NRC Operating License No. NPF-37 and to the discussion of our findings with Mr. L. Sues at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original signed by D. H. Danielson (for)

J. J. Harrison, Chief Engineering Branch

Enclosure: Inspection Report No. 50-454 (88017 (DRS))

See Attached Distribution

8810250443 881020 PDR ADDCK 05000454 Q PNU

RIII #Ward/jk 10/19/88 Hinds 10/20/88 Danielson 10//9/88 RIII Marrison 10/3e/88

Distribution

cc w/enclosure:
T. J. Maiman, Vice President,
PWR Operations
H. Bliss, Nuclear
Licensing Manager
R. Pleniewicz, Station Manager
DCD/DCB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII Byron
Resident Inspector, RIII
Braidwood
D. W. Cassel, Jr., Esq.
Richard Hubbard
J. W. McCaffrey, Chief, Public
Utilities Division
Diane Chavez, DAARE/SAFE
L. Olshan, LPM, NRR
H. S. Taylor, Quality Assurance
Division