DCT 1 7 1008

In Reply Refer To: Docket: 50-267/88-24

Public Service Company of Colorado ATTN: Robert O. Williams, Jr.

Vice President, Nuclear Operations

2420 W. 26th Avenue, Suite 15c

Denver, Colorado 80211

Gentlemen:

This refers to the inspection conducted by Messers H. F. Bundy, and T. O. McKernon of this office during the period September 26-30, 1988, of activities authorized by NRC Cherating License DPR-34 for Fort. St. Vrain, and to the discussion of our findings with you and other members of your staff at the conclusion of the inspection.

Areas examined during the inspection included surveillance and modification testing. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the NRC inspectors. The inspection findings are documented in the enclosed inspection report.

Within the scope of the inspection, no violations or deviations were identified.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

Original Signed By A. B. Beach

L. J. Callan, Director Division of Reactor Projects

Enclosure: (see next page)

G-HFBundy: gb

CIPMcKernon 10/12/88

10/13/88

10/17/88

Enclosure: Appendix - NRC Inspection Report 50-267/88-24

cc w/enclosure: Fort St. Vrain Nuclear Station Manager, Nuclear Production Division 16805 WCR 19½ Platteville, Colorado 80651

Fort St. Vrain Nuclear Station P. Tomlinson, Manager, Quality Assurance Division (same address)

Colorado Radiation Control Program Director Colorado Public Utilities Commission

bcc to DMB (IEO1) - DRS & DRP bcc distrib. by RIV:

*RRI *Section Chief (DRP/B)

*RPB-DRSS
*MIS System

*K. Heitner, NRR Project Manager

*DRS

*H. Bundy *W. C. Seidle *R. D. Martin, RA

*Project Engineer, DRP/B Lisa Shea, RM/ALF

*RSTS Operator

*RIV File

*DRP

*T. McKernon

*w/766