

ENCLOSURE 2

NOTICE OF DEVIATION

Duke Power Company
McGuire Units 1 and 2

Docket Nos. 50-369 and 50-370
License Nos. NPF-9 and NPF-17


The following deviation was identified during a Nuclear Regulatory Commission (NRC) inspection conducted on April 23 - May 20, 1988.

In a response dated May 29, 1987, to Violation 87-04-01 issued on April 29, 1987, the licensee stated that "Training and staff licensed personnel are no longer permitted to make an operability determination. Operability determinations by training instructors and staff SRO's must be made with the concurrence of a regular shift SRO".

Contrary to the above, only a staff SRO was involved with the operability determination associated with Problem Investigation Report O-M88-0089 concerning turbine driven auxiliary feedwater pump operability.

Please provide in writing within 30 days of the date of this Notice a description of corrective actions regarding this deviation, actions taken to avoid further deviations, and the dates when these actions were or will be completed.

FOR THE NUCLEAR REGULATORY COMMISSION


Virgil L. Brownlee, Chief
Reactor Projects Branch 3
Division of Reactor Projects

Dated at Atlanta, Georgia
this 6 day of June 1988

8806200485 880606
PDR ADOCK 05000369
Q ncn