

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

June 13, 1988

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Subject: McGuire Nuclear Station
Unit 2
Docket No. 50-370

Gentlemen:

On May 12, 1988, the auxiliary feedwater system was aligned to its assured source (nuclear service water system) during testing. This was reported to the NRC per 10 CFR 50.72 b.2.(ii) and is reportable per 10 CFR 50.73 a.2.(iv), with the Licensee Event Report due June 13, 1988. All concerns surrounding this incident have not yet been resolved; consequently the LER will be delayed until July 13, 1988.

Very truly yours,

Hal B. Tucker, for
Hal B. Tucker

JBD/273/bhp

cc: Dr. J. Nelson Grace
Regional Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta St., NW, Suite 2900
Atlanta, GA 30323

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, GA 30339

M&M Nuclear Consultants
1221 Avenue of the Americas
New York, NY 10020

American Nuclear Insurers
c/o Dottie Sherman, ANI Library
The Exchange, Suite 245
270 Farmington Avenue
Farmington, CT 06032

Mr. Darl Hood
U.S. Nuclear Regulatory Commission
Office of Nuclear Reactor Regulation
Washington, D.C. 20555

Mr. W.T. Orders
NRC Resident Inspector
McGuire Nuclear Station

*TE22
1/0*