

Docket Nos. 030-11599  
030-10366

License Nos. 37-16101-02  
37-16101-01

August 16, 1988

John E. Glenn  
Nuclear Materials Safety Section  
475 Aliendale Road  
King of Prussia, PA 19406

Mr. Glenn:

In response to your letter of August 8, 1988, we have taken the following actions to prevent a future recurrence of the aforementioned violations.

- A. Additional shielding has been placed around the source of radiation that was causing the higher than allowed reading in the hallway. This area will also be monitored periodically.
- B. The dose calibrator has been checked for linearity and will continue to be checked. A schedule of the next due date has been prominently located on the instrument as a reminder.
- C. A dedicated check source is available for use with the survey meter and the exposure rate will be conspicuously noted on the instrument. This procedure has been added to our calibration procedure to assure adherence.
- D. All employees have been instructed as to the necessity to protect their badges from loss.
- E. A specific section labelled "hot trash" has been added to the survey manual. Technologists have been instructed as to the need to use this separate column to denote the results of this survey.

Sincerely,

*Sister Jean Mohl*

Sister Jean Mohl, President  
Divine Providence Hospital

SJM/lgw