

November 13, 1998

U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Gentlemen:


Subject: Docket No. 50-361 and 50-362  
30-Day Report  
Licensee Event Report No. 1998-022  
San Onofre Nuclear Generating Station, Unit 2 and 3

This letter provides Licensee Event Report (LER) 1998-022 for an occurrence of the Shutdown Cooling System being inoperable due to an inadequate surveillance test. Because this condition involves similar systems, cause, and corrective actions applicable to both Units 2 and 3, a single report for Unit 2 is being submitted in accordance with NUREG-1022, Rev 1.

The health and safety of neither the public nor plant personnel were affected by this occurrence.

Any actions listed are intended to ensure continued compliance with existing commitments as discussed in applicable licensing documents; this LER contains no new commitments. If you require any additional information, please so advise.

Sincerely,



11  
IE22

9811180255 981113  
PDR ADOCK 05000361  
S PDR

LER No. 1998-022

cc: E. W. Merschoff, Regional Administrator, NRC Region IV  
J. A. Sloan, NRC Senior Resident Inspector, Units 2 and 3  
Institute of Nuclear Power Operations (INPO)

P. O. Box 128  
San Clemente, CA 92674-0128  
714-368-6255  
Fax 714-368-6183

170180