

### LICENSEE EVENT REPORT (LER)

FACILITY NAME (1): **VOGTLE UNIT 1** DOCKET NUMBER (2): **05000424** PAGE (3): **1 OF 03**

TITLE (4): **INADEQUATE PROCEDURE LEADS TO PLANT OPERATION OUTSIDE OF TECH. SPECS.**

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)													
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)											
1	0	3	8	8	8	0	3	1	0	1	1	2	8	6	8			0	5	0	0	0
																		0	5	0	0	0

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5. (Check one or more of the following) (11)

OPERATING MODE (9): <b>6</b>	<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.406(e)	<input type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)
POWER LEVEL (10): <b>01010</b>	<input type="checkbox"/> 20.406(a)(1)(i)	<input type="checkbox"/> 50.36(a)(1)	<input type="checkbox"/> 50.73(a)(2)(v)	<input type="checkbox"/> 73.71(c)
	<input type="checkbox"/> 20.406(a)(1)(ii)	<input type="checkbox"/> 50.36(a)(2)	<input type="checkbox"/> 50.73(a)(2)(vi)	<input type="checkbox"/> OTHER (Specify in Abstract below and in Text - NRC Form 365A)
	<input type="checkbox"/> 20.406(a)(1)(iii)	<input checked="" type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(a)(2)(vii)(A)	
	<input type="checkbox"/> 20.406(a)(1)(iv)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(vii)(B)	
	<input type="checkbox"/> 20.406(a)(1)(v)	<input type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 50.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12):

NAME: **J. E. Swartzwelder, Nuclear Safety and Compliance Manager** TELEPHONE NUMBER: **404 826-3618**

AREA CODE: **404**

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS

SUPPLEMENTAL REPORT EXPECTED (14):  YES (If yes, complete EXPECTED SUBMISSION DATE)  NO

EXPECTED SUBMISSION DATE (15): MONTH  DAY  YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On 10-30-88, core alterations were suspended while a Train A loss of offsite power test was being conducted. While this occurs, the actuation of Train A Engineered Safety Features (ESF's) is blocked. When the test was completed, core alterations resumed. At 0646 CST, during shift change and turnover, control room personnel noticed that the protection system "Train A Trouble" annunciator was lit and discovered that the input error inhibit switch on the Solid State Protection System (SSPS) logic test panel was in the "inhibit" position. The Containment Ventilation Isolation (CVI) system is not operable unless both Train A SSPS and Train B SSPS are operable. Also, direct access to the outside atmosphere was not blocked by closing the containment ventilation penetrations. Therefore, the plant was operating in a condition outside of the Tech. Specs. and core alterations were halted. By 0715 CST, the input error inhibit switch was returned to its "normal" position, SSPS Train A was returned to operable status and core alterations were resumed.

The testing procedure, which did not provide for restoration of the input error inhibit switch to its "normal" position, will be corrected before the test is conducted again.

8812040273 881128  
PDR ADOCK 05000424  
PDC

JE22  
11

Georgia Power Company  
333 Piedmont Avenue  
Atlanta, Georgia 30308  
Telephone 404 526-3195

Mailing Address:  
40 Inverness Center Parkway  
Post Office Box 1295  
Birmingham, Alabama 35201  
Telephone 205 866-5581

*The southern electric system*

W. G. Hairston, III  
Senior Vice President  
Nuclear Operations

ELV-00046  
X7GJ17-V310  
0796D

December 1 1988

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D. C. 20555

NRD DOCKET 50-424  
OPERATING LICENSE NPF-68  
PLANT VOGTLE - UNIT 1  
LICENSEE EVENT REPORT  
INADEQUATE PROCEDURE LEADS TO PLANT  
OPERATION OUTSIDE OF TECH. SPECS.

Gentlemen:

In accordance with 10 CFR 50.73, Georgia Power Company hereby submits the enclosed revised page 1 relating to an event which occurred on October 30, 1988. The original version inadvertently indicated that a supplemental report would be submitted on January 25, 1989.

Sincerely,

*W. G. Hairston III*  
W. G. Hairston, III

WBS/ijb

Enclosure: LER 50-424/1988-031-01

c: Georgia Power Company  
Mr. P. D. Rice  
Mr. G. Bockhold, Jr.  
Mr. M. Sheibani  
Mr. J. P. Kane  
VOGTLE-NORMS  
GO-NORMS

U. S. Nuclear Regulatory Commission  
Mr. M. L. Ernst, Acting Regional Administrator  
Mr. J. B. Hopkins, Licensing Project Manager, NRR (2 copies)  
Mr. J. F. Rogge, Senior Resident Inspector - Operations, Vogtle

*IE22  
1/1*