Duquesne Light Company Beaver Valley Power Station

PO Box 4 Shippingport, PA 15077-0004

JOHN D. SIEBER Vice President Nuclear Group

1412: 643 5255

November 21, 1988

U. S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555

Beaver Valley Power Station, Unit No. 1 Reference: Docket No. 50-334, License No. DPR-66 Steam Generator Tube Inservice Inspection Results Report

Gentlemen:

Attached please find the results of the Beaver Valley Unit No. 1 Sixth Refueling Outage Steam Generator Tube Inservice Inspection Report. This report contains:

- 1. the number and extent of tubes inspected,
- 2. location and percent of wall-thickness penetration for each indication of an imperfection, and
- 3. identification of tubes plugged.

This report is being submitted in accordance with plant Technical Specification 4.4.5.5.

If you have any questions, please contact me or members of my staff.

Very truly yours,

Seller J. D. Sieber

Vice President Nuclear Group

Attachment

Mr. J. Beall, Sr. Resident Inspector cci Mr. W. T. Russell, NRC Region I Administrator Mr. P. Tam, Sr. Project Manager Director, Safety Evaluation & Control (VEPCO)

8812080232 8811 PDR ADOCK 0500