



PECO NUCLEAR

A Unit of PECO Energy

Robert W. Boyce
Plant Manager
Limerick Generating Station

PECO Energy Company
Limerick Generating Station
PO Box 2300
Sanatoga, PA 19464-0920
610 718 2000

10CFR50.73

July 7, 1997
Docket No. 50-353
License No. NPF-85

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

Subject: Licensee Event Report
Limerick Generating Station - Unit 2

This LER reports a noncompliance with the requirements of Facility Operating License NPF-85 condition 2.C.1, when a plant transient resulted in exceeding licensed thermal power by 2.4%. The plant transient was caused by an EHC malfunction that caused a reactor pressure perturbation. The cause of the EHC malfunction has not yet been determined.

Reference: Docket No. 50-353
Report Number: 2-97-005
Revision Number: 00
Event Date: June 5, 1997
Report Date: July 7, 1997
Facility: Limerick Generating Station
PO Box 2300, Sanatoga, PA
19464-2300

1/1
Terry

This report is being submitted pursuant to the requirements of Facility Operating License No. NPF-85 Condition 2.E.

Very truly yours,

TST/cah

cc: H. J. Miller, Administrator Region I, USNRC
N. S. Perry, USNRC Senior Resident Inspector, LGS

9707230020 970707
PDR ADOCK 05000353
S PDR

